

2026 Lxor

p: owner states- rear shade don't go up
c: broke
r: checked to verify that the shade is not fuctional and need to order a new shade
Line2- 0.3 approved.

2024 Plateau

complaint 1: c/s: passenger rear blind not retracting properly. makes clicking sounds.
cause: the back passenger side blind has an internal failure, broken parts inside of it. there is something rolling around inside the tube making noise while operating.
correction: r & r blind
requested: 1 hr. + part Line1- 0.3 approved to R&R shade.

complaint 2: c/s: rear back shade is coming apart at the end and hops when retracting , no longer is smooth.
cause: the back blind for the back window does not stay down and is jerky while going up - internal failure in the tube. one corner is coming apart on the pool handle.
correction: r & r blind
requested: 1 hr. + part Line2-0.3 approved to R&R shade.

complaint 3: c/s: driverside rear shade starting to come apart at the bottom.
cause: found the corner at the bottom of the shade peeling away from itself; adhesive is failing
correction: need to either reglue bottom corner or replace shade
Line3-0.3 approved to R&R shade.