



SSM 55177 2025-2026 Maverick, 2026 Bronco Sport - Equipped With 8-inch Display IPC - Fuel Gauge Displays One Mark Below The Full Fuel Level When The Fuel Tank Is Full

Some 2025-2026 Maverick and 2026 Bronco Sport vehicles equipped with an 8-inch instrument panel cluster (IPC) display may exhibit a condition where the fuel gauge displays one mark below the full fuel level when the fuel tank is full. This may be due to the software in the IPC. To correct the condition, download and run the "IPC - Instrument Panel Cluster (IPC) Software Update" application using the latest software level of the Ford Diagnosis and Repair System (FDRS) scan tool. For claiming, use causal part 10849 and labor operations 12651D and IPC.