## GM CUSTOMER CARE AND AFTERSALES DCS3328 URGENT - DISTRIBUTE IMMEDIATELY

Date: September 2, 2014

Subject: 14152B - Safety Recall

Transmission Shift Cable Fracture Revised Part Information Section

Models: 2004-2007 Chevrolet Malibu Maxx, 2004-2008 Chevrolet Malibu,

2005-2008 Pontiac G6, 2007-2008 Saturn AURA Equipped with

4-Speed Automatic Transmission (ME7/MN5)

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and

Service Director, Parts Manager, Used Vehicle Sales Manager,

and Warranty Administrator

This recall is being administered in phases due to part availability. The first phase covered AURA vehicles. This second phases covers the Pontiac G6 vehicles. The Part Information section has been revised to include G6 parts. Please discard all copies of bulletin 14152A.

## **Customer Letter Mailing**

The customer letter mailing for Pontiac G6 customers will begin in mid-September 2014.

END OF MESSAGE GM CUSTOMER CARE AND AFTERSALES