

GM CUSTOMER CARE AND AFTERSALES
DCS3196
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2014

Subject: 14152A – Safety Recall
Transmission Shift Cable Fracture
Revised Warranty Transaction Information Section

Models: 2004-07 Chevrolet Malibu Maxx and Saturn AURA; 2004-08
Chevrolet Malibu; 2005-08 Pontiac G6 Equipped with 4-Speed
Automatic Transmission (ME7/MN5)

To: All GM Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager,
and Warranty Administrator

The Warranty Transaction Information section has been revised. The repair labor code has changed. Please discard all copies of bulletin 14152.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES