

Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



IMPORTANT SAFETY RECALL

August 2014

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists 2004 - 2008 model year Chevrolet Aveo vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- This notice applies to your 2004 - 2008 model year Chevrolet Aveo, VIN: _____.
- Your vehicle is involved in GM safety recall 14093.

Why is your vehicle being recalled?

Heat generated within the headlamp switch or daytime running lamp (DRL) module, which are both located on or near the left side of the steering column, could melt the headlamp switch or DRL module and cause a fire.

What will we do?

PARTS ARE NOT CURRENTLY AVAILABLE. We are working as quickly as possible to correct this condition. When a repair and parts are available, we will send you another letter asking you to take your vehicle to your GM dealer to have your vehicle serviced. This service will be performed for you at **no charge**.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
Guam	65-6267-1752	

Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jim Moloney
General Director,
Customer and Relationship Services

Enclosure
GM Recall #14093