## **Recall Quarterly Report**

14V-577

**Manufacturer Name:** Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 14V-577 /WQN-50

**Recall Subject:** Trailer Hitch Assembly may be Incorrectly Torqued

**Owner Notification Beginning Date :** OCT 07, 2014

**Owner Notification End Date:** APR 15, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 12, 2016	2016-1	56	55	1	0
5	JAN 13, 2016	2015-4	56	54	0	0
4	OCT 15, 2015	2015-3	56	54	0	0
3	JUL 10, 2015	2015-2	56	52	0	0
2	APR 16, 2015	2015-1	56	46	0	0
1	JAN 19, 2015	2014-4	56	42	0	0

This Document Last Updated: APR 12, 2016

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.