

GM CUSTOMER CARE AND AFTERSALES
DCS3424
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 29, 2014

Subject: 14456A – Product Safety Recall - Revised
Hood Striker Corrosion
Revised Part Information Section

Models: 2013-2015 Chevrolet Spark

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager and Warranty Administrator

The Part Information section has been revised. Dealers can now order parts from GMCCA. Please discard all copies of bulletin 14456.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES