

GM CUSTOMER CARE AND AFTERSALES  
DCS3521  
URGENT - DISTRIBUTE IMMEDIATELY

Date: January 30, 2015

Subject: 14515B - Safety Recall  
Chassis Electronic Control Module Internal Contamination  
Parts and Labor Section Revised

Models: 2014 Buick Enclave  
2013-2014 Cadillac CTS (VIN D), Escalade, Escalade ESV  
2013-2014 Chevrolet Captiva, Suburban, Tahoe  
2014 Chevrolet Express, Impala (VIN W), Silverado HD, Traverse  
2014 GMC Acadia, Savana, Sierra HD  
2013-2014 GMC Yukon, Yukon XL  
Built With a Suspect Chassis Electronic Module  
and  
2007-2012 Various GM Makes and Models  
Serviced With a Suspect Chassis Electronic Module

To: All General Motors Dealers

Attention: Dealer, Dealer Principal, General Manager, General Sales  
Manager, New Vehicle Sales Manager, Parts and Service Director,  
Parts Manager, Service Manager, and Warranty Administrator

General Motors is releasing Safety Recall 14515B today.

This bulletin is being revised to clarify module use with RPO JL1, and to add 3500 series pickup trucks to the labor time chart. Please discard all copies of bulletin 14515A.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES