



NUMBER: 08-019-15

GROUP: Electrical

DATE: March 04, 2015

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS BULLETIN SUPERSEDES SERVICE BULLETIN 08-100-14, DATED DECEMBER 02, 2014 WHICH SHOULD BE REMOVED FROM YOUR FILES. THIS IS A COMPLETE REVISION AND NO **ASTERISKS HAVE BEEN USED TO HIGHLIGHT REVISIONS.**

SUBJECT:

Loss Of Power Heated Mirror Function - Recall P61

OVERVIEW:

Refer to service procedures outlined in recall P61.

MODELS:

2011 - 2013 (JK) Jeep Wrangler

NOTE: This bulletin applies to vehicles built on or after February 16, 2010 (MDH 0216XX) and on or before July 19, 2013 (MDH 0719XX) equipped with Power Heated Side Mirrors (Sales Code GTB).

DISCUSSION:

Vehicles covered under the TSB 08-100-14 will now be covered under Recall P61 and should follow all service procedures and labor times outlined in the recall.

POLICY:

Information only.