

**Subarunet Announcement**



**To: All Subaru Retailers**  
**From: Subaru of America, Inc.**  
**Date: November 1, 2017**

**Takata Air Bag Inflator Recall Announcement – Owner Re-Notification WQR53 and WQP51 scheduled for November 8, 2017**

In accordance with the priority group assignments and completion rate deadlines established by NHTSA, we will be re-notifying owners whose vehicles are in the top three highest risk priority groups listed below:

- Priority Group 1 – WQR53: vehicles with HAH registration history
- Priority Group 2 – WQP51: vehicles with HAH registration history
- Priority Group 3 – WQR53: vehicles with non-HAH registration history

The vehicles included in the top three highest risk priority groups are as follows:

- 2003-2005 MY Baja
- 2004-2005 MY Impreza (including WRX)
- 2003-2008 MY Legacy
- 2003-2008 MY Outback

Affected VIN lists for this mailing have been distributed to each Zone Office for this owner re-notification.

It is imperative that each retailer reach out to their respective owners to get these repairs completed. The owner notification letters are scheduled to be mailed on November 8, 2017.

**Important: Retailer affected VIN lists include owner information for vehicles affected by this safety recall. This information will enable retailers to follow up with owners of affected vehicles. The lists contain owners' information obtained from State Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with the recall is unlawful. Accordingly, retailers must limit the use of these lists to the purpose of completion of this safety recall and must maintain these lists in the strictest of confidence. In addition, retailers must comply with all applicable federal and state privacy laws and regulations pertaining to those individuals and entities in possession of this information.**