

# Recall Quarterly Report

# 15V-323

**Manufacturer Name :** Subaru of America, Inc.

**NHTSA Recall No. / MFR Recall No. :** 15V-323 /WQR-53

**Recall Subject :** Passenger Side Front Air Bag Inflator may Rupture

**Owner Notification Beginning Date :** JUN 17, 2015

**Owner Notification End Date:** DEC 23, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
12	APR 20, 2018	2018-1	432,016	279,488	0	31,019
11	JAN 11, 2018	2017-4	432,016	266,367	0	29,304
10	OCT 20, 2017	2017-3	432,016	240,999	0	28,492
9	JUL 14, 2017	2017-2	432,016	208,935	8,329	28,491
8	APR 13, 2017	2017-1	432,016	188,618	0	0
7	JAN 23, 2017	2016-4	432,016	162,303	0	0
6	OCT 11, 2016	2016-3	432,016	121,456	0	0
5	JUL 18, 2016	2016-2	432,016	64,366	0	0
4	APR 12, 2016	2016-1	432,016	30,189	0	0
3	JAN 14, 2016	2015-4	432,016	15,415	0	0
2	OCT 15, 2015	2015-3	89,649	10,355	0	0
1	JUL 10, 2015	2015-2	81,092	2,339	0	0

This Document Last Updated : APR 26, 2018

## Definitions :

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.