OMB Control No.: 2127-0004

Recall Quarterly Report

15V-323

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 15V-323 /WQR-53

Recall Subject : Passenger Side Front Air Bag Inflator may Rupture

Owner Notification Beginning Date : JUN 17, 2015

Owner Notification End Date: SEP 30, 2015



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
2	OCT 15, 2015	2015-3	89,649	10,355	0	0
1	JUL 10, 2015	2015-2	81,092	2,339	0	0

This Document Last Updated: OCT 16, 2015

Definitions:

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.