

GM CUSTOMER CARE AND AFTERSALES
DCS3701
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2015

Subject: Upcoming Safety Recall 15042
HVAC Connector Wire Failure

Models: 2006-2010 Hummer H3
2009-2010 Hummer H3T

To: All General Motors Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, Used Vehicle Sales Manager

General Motors has notified the National Highway Traffic Safety Administration (NHTSA) about an upcoming safety recall that involves 2006-2010 Hummer H3 and 2009-2010 Hummer H3T model year vehicles. The GM recall number is 15042.

General Motors has decided that a defect which relates to motor vehicle safety exists in 2006-2010 model year Hummer H3 and 2009-2010 Hummer H3T vehicles. The connector module that controls the blower motor speed in the heat/vent/air conditioning (HVAC) system may overheat under extended operational periods at high and medium-high blower speeds. If this condition occurs, there is the risk that the heat generated could melt the plastic surrounding the connector module, which increases the risk of a fire.

Parts are not currently available, but when parts are available, dealers are to replace the female connector and harness.

This is a courtesy notification to dealers. Dealers will be advised when the recall bulletin is scheduled for release.

The Investigate Vehicle History screen in the Global Warranty Management system will be updated for this upcoming safety recall. This action has been taken to assist dealers with determining which vehicles are involved so they can properly respond to customer inquiries. Please note the "N/A" under Release Date and the "Incomplete – Remedy Not Yet Available" message under Status. This means release of the recall bulletin is still pending and dealers should not attempt to perform any repairs at this time.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES