

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS3931
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 12, 2016
Subject: 15042 - Safety Recall
HVAC Connector Wire Failure
Models: 2006-2010 HUMMER H3
2009-2010 HUMMER H3T
To: All General Motors Dealers

General Motors is releasing Safety Recall 15042 today. The total number of U.S. vehicles involved is approximately 165,000. Please see the attached bulletin for details.

Vehicles involved in this recall were placed on stop delivery June 26, 2015. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

Customer Letter Mailing

The customer letter mailing will begin on February 26, 2016.

Global Warranty Management (GWM)

The Investigate Vehicle History (IVH) screen in the GWM system will be updated February 12, 2016. A list of involved vehicles is attached to this message. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS