

DRV Suites Curb Side Front Reflector


Description

It has been decided the vehicles in this recall population may have been manufactured with the forward reflector on the door side of the camper located above the maximum height allowable by a range of 8 to 10 inches.

Inspection & Repair

Identify the reflector locations on the curb or Door side of camper.

1. This is the current location of the reflector that is incorrectly placed.



2. Where to install the reflector tape that is being sent to you.



3. Location to install the reflective tape, place one on each side approximately 48” from the ground, any position in this general area is acceptable as long as the reflector is below 60”.
4. Clean any dirt from the sidewall, peel backing from tape and apply. Apply starting on one end of tape and slowly smooth the tape as you apply working from front to back.

Parts

Reflector Tape Part # 0279982

Warranty

Dealers installing the Reflector may file Recall Repair warranty claim using warranty code 99.02.05.A, for 0.1 hours.

Please refer all questions and authorization requests to DRV Warranty/Service Department. 260-562-3500