

CERTAIN 2015-2016 MODEL YEAR F-SUPER DUTY CHASSIS CAB VEHICLES EQUIPPED WITH A 6.7L DIESEL ENGINE AND SERVICED WITH FUEL INJECTORS OR FUEL SYSTEM KITS — INSPECT AND REPLACE FUEL SYSTEM COMPONENTS

OVERVIEW

Some of the affected vehicles could have been serviced with fuel system components not intended for use in a chassis cab application, due to a parts catalog error. Suspect parts are fuel injector kits and fuel system kits. Dealers are to determine if the VIN is included in Attachment IV, and if so, install a *new* high pressure pump, all 8 injectors and fuel injector supply tubes. All other vehicles will be inspected, and any incorrect injectors will be replaced as needed.

INSPECTION AND SERVICE PROCEDURE

1. Reference Attachment IV to determine if a *new* fuel system kit is required:

NOTE: Repairs covered under this recall are the result of a parts cataloging error rather than fuel system contamination. As a result, some of the components included in the fuel system kit will not be used in the repair.

- If the VIN is on Attachment IV, the vehicle **DOES** require a *new* fuel system kit. Please install only the high pressure pump, all eight fuel injectors and the fuel injector supply tubes following the Workshop Manual (WSM) procedures in Section 303-04C.
 - If the VIN is not on Attachment IV, the vehicle **DOES NOT** require a *new* fuel system kit. Proceed to Step 2.
2. Remove the RH and LH fender splash shields. Please follow the WSM procedures in Section 501-02, Fender Splash Shield.
 3. Remove the five RH and four LH engine sound shield retainers and the RH and LH engine sound shields from the valve covers.



4. Inspect all fuel injectors for the presence of a gray fuel return port. See Figure 1.

- Fuel injectors with a gray fuel return port are not correct for the vehicle and must be replaced. Please follow the WSM procedures in Section 303-04C, Fuel Injectors.
- Fuel injectors with blue fuel return ports are correct for the vehicle and do not need to be replaced. Proceed to Step 5.




FIGURE 1

5. Install the RH and LH engine sound shields onto the valve covers and install the five RH and four LH engine sound shield retainers.
6. Install the RH and LH fender splash shields. Please follow the WSM procedures in Section 501-02, Fender Splash Shield.

