



Date: January 30, 2017  
To: Audi Dealer Principal, Service Manager, Warranty Administrator, Sales Manager & Parts Manager, General Manager  
From: Audi Customer Protection  
Subject: Advance Notice Safety Recall 69P2 – Autoliv Igniters  
Certain 2017-2018 MY Audi Vehicles

Audi has notified NHTSA and Transport Canada about the upcoming safety recall described in this letter.

<b>CODE</b>	69P2
<b>AFFECTED VEHICLES</b>	Certain 2017-2018 MY Audi vehicles: USA: 2017 MY Audi A4 allroad, A4 Sedan, A6, A7, Q7 & 2018 MY Audi Q5 Canada: 2017 MY Audi A4 allroad, A4 Sedan, A6, A7, Q7
<b>RECALL DESCRIPTION</b>	Affected vehicles have airbag and/or pretensioner igniter(s) manufactured by Autoliv. The affected igniter(s) may not meet manufacturing specifications. In a crash where airbag and/or pretensioner deployment is needed, an igniter may not deploy, increasing the risk of injury.
<b>CORRECTIVE ACTION</b>	Dealers will replace the affected airbags.
<b>REPAIR INFORMATION</b>	On or about February 1, 2017 affected vehicles will be identified in ELSA and VIN lookup. Repair information will be provided to dealers when parts and repair instructions become available to support this recall.

If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Audi Public Relations.

Audi Customer Protection