



## VOLKSWAGEN DEALERSHIP COMMUNICATION

Date: January 30, 2017  
To: Dealer Principal, Sales Manager, Service Manager, Parts Manager and Warranty Administrator  
Subject: Advance Notice – Safety Recall 69P4 - Autoliv Igniters  
Certain 2016-2017 MY Volkswagen Vehicles

### IMPORTANT NOTICE TO DEALERS - FOR IMMEDIATE DISTRIBUTION

Volkswagen has notified NHTSA and Transport Canada about the upcoming safety recall described in this letter.

<b>CODE</b>	69P4
<b>AFFECTED VEHICLES</b>	Certain 2016-2017 MY Volkswagen vehicles: USA: 2016 MY Volkswagen e-Golf, 2017 MY Volkswagen Golf and Tiguan Canada: 2017 MY Volkswagen Golf & Tiguan
<b>RECALL DESCRIPTION</b>	Affected vehicles have airbag igniter(s) manufactured by Autoliv. The affected igniter(s) may not meet manufacturing specifications. In a crash where airbag deployment is needed, an igniter may not deploy, increasing the risk of injury.
<b>CORRECTIVE ACTION</b>	Dealers will replace affected airbags.
<b>REPAIR INFORMATION</b>	On or about February 1, 2017 affected vehicles will be identified in ELSA and VIN lookup.  Repair information will be provided to dealers when parts and repair instructions become available to support this recall.

If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Volkswagen Public Relations.

Volkswagen Customer Protection