

# The Goodyear Tire & Rubber Company

Akron, Ohio 44316-0001

September 1, 2016

## IMPORTANT SAFETY RECALL

### Dunlop P205/70R15 SP50

Dear Dealer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act. During a random compliance test, one Dunlop P205/70R15 tire exhibited a tread element chunk during the low inflation pressure performance portion of the endurance test and, therefore, fails to comply with FMVSS 139, "New Pneumatic Radial tires for Light Vehicles." As a result, The Goodyear Tire & Rubber Company is conducting a voluntary recall of Dunlop P205/70R15 SP50 tires manufactured from week 4912 through week 0314 at our Lawton, OK plant (the "subject tires").

**First, please check your inventory for any unsold subject tires. Any such tires found in inventory must not be sold and must be returned through the warranty return process described in the Product Service Bulletin which is attached.** We ask that you contact any consumers or dealers who may have purchased one of these tires from you and ask for the tires to be returned for replacement. The Product Service Bulletin provides details about this program. We are also attaching a consumer letter that can be forwarded to your customers that purchased these tires and a sample letter that can be included using your letterhead.

### DESCRIPTION OF TIRES COVERED

Size	Type	Product Code	DOT Date Range (Week/Yr)
P205/70R15	Dunlop SP50	263002370	M6MOLTER4912 through M6MOLTER0314



If you have questions, please contact your National Field Manager Product Service. Contact information for your National Field Manager Product Service, can be found in the Adjustment Procedure Guide or on Tire-HQ.

If further assistance is required for any reason, including difficulty in obtaining free replacement tires, please contact Goodyear Consumer Relations by calling toll free 1-800-592-3267.

Sincerely,

The Goodyear Tire & Rubber Company