OMB Control No.: 2127-0004

Recall Quarterly Report

16V-738

Manufacturer Name: Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No.: 16V-738 /WTM-73

Recall Subject: Power Relay may Fail Allowing Air Pump to Overheat

Owner Notification Beginning Date : DEC 16, 2016

Owner Notification End Date: DEC 16, 2016



| Report # | Submission Date | Report Quarter | Recall Population | Total Remedied | Total Unreachable | Total Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 2 | APR 12, 2017 | 2017-1 | 100,127 | 36,259 | 0 | 0 |
| 1 | JAN 23, 2017 | 2016-4 | 100,127 | 15,807 | 0 | 0 |

This Document Last Updated: MAY 17, 2017

Definitions:

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the $3^{\rm rd}$ quarter of 2012).

Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.