

Recall Quarterly Report

16V-738

Manufacturer Name : Subaru of America, Inc.

NHTSA Recall No. / MFR Recall No. : 16V-738 / WTM-73

Recall Subject : Power Relay may Fail Allowing Air Pump to Overheat

Owner Notification Beginning Date : DEC 16, 2016

Owner Notification End Date: DEC 16, 2016



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
6	APR 20, 2018	2018-1	100,127	60,981	3,801	0
5	JAN 08, 2018	2017-4	100,127	55,512	3,801	0
4	OCT 06, 2017	2017-3	100,127	49,674	3,801	0
3	JUL 14, 2017	2017-2	100,127	44,092	3,801	0
2	APR 12, 2017	2017-1	100,127	36,259	0	0
1	JAN 23, 2017	2016-4	100,127	15,807	0	0

This Document Last Updated : APR 23, 2018

Definitions :

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3rd quarter of 2012).

Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.