

IMPORTANT SAFETY RECALL 2016120005

This INTERIM notice applies to your vehicle, WDDUG6DB8FA123456

Electric Power Steering Control Unit NHTSA Recall # 16V899 Mercedes-Benz USA, LLC Christian Treiber Vice President Customer Services

January, 2017

2016120005 WDDUG6DB8FA123456 Daniel Selke 1 Mercedes Drive Montvale, NJ 07645

Dear Mercedes-Benz Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Daimler AG (DAG), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 2017 Mercedes-Benz E-Class Coupe (207 platform) vehicles. The purpose of this letter is to explain what the recall is about, what we are doing to correct it, and when parts will be available.

WE SENT YOU THIS NOTICE BECAUSE WE ARE CONCERNED ABOUT YOUR SAFETY.

Certain Model Year 2017 E-Class Coupe vehicles might have been built with electric power steering control units that were equipped with improperly soldered contacts. If the affected pins lose complete electrical contact, the vehicle's electric power steering may deactivate, increasing the risk of a crash. In addition, the complete loss of electrical connection could lead to a short circuit within the control unit, increasing the risk of a fire.

We are working to obtain the necessary parts to correct this condition as quickly as possible. As parts become available, we will send you another letter asking you to take your vehicle to an authorized Mercedes-Benz dealer to have the issue corrected free of charge.

Should you have any concerns or questions regarding your vehicle before you receive the next recall letter, please contact an authorized Mercedes-Benz dealer. If for any reason a dealer is unable to remedy your situation, we are always happy to hear from you. Please contact us at 1-(800) FOR-MERCEDES (1-800-367-6372). A new vehicle identification number (VIN)-based recall lookup tool, on our MBUSA.com website, now offers a search function that will indicate whether a vehicle has been subject to a safety recall, and whether that vehicle has had the free remedy performed. See www.MBUSA.com/recall.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee within 10 days to comply with federal regulations.

If a Mercedes-Benz dealer for any reason is unable to remedy the situation without charge, or within a reasonable amount of time, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We regret any inconvenience this situation may cause you.

Sincerely,

Mercedes-Benz USA, LLC 303 Perimeter Center North Suite 202 Atlanta, GA 30346 Phone (770) 705-0600 Fax (770) 705-0117 www.MBUSA.com

IMPORTANT

VIN: WDDUG6DB8FA123456

pla	If for any reason YOU NO LONGER OWN THIS VEHICLE OR have a CHANGE OF ADDRESS, please COMPLETE THE SECTION BELOW, place in the ENCLOSED ENVELOPE, and DROP IN ANY MAIL BOX. If possible, provide the name and address of the present owner so that we may contact them.																												
	□ EXPORTED□ LEASE, VEHICLE RETURNED□ SCRAPPED																SOL STO OTH	LEN											
	□ NEW OWNER INFORMATION															MY	MY NEW NAME OR ADDRESS IS:												
Last Name, First Name																													
St	Street																								Ар	t			
																					de			energy there					
Cit	City														•	State ZI										P			
Email Address																													
																		2	***										
Phone (numbers only) Mobile (numbers only)																													

THANK YOU FOR YOUR COOPERATION

Signature

Date