

## IMPORTANT SAFETY RECALL



COOPER TIRE & RUBBER COMPANY  
Findlay, Ohio 45840 419-423-1321

February 10, 2017

Dear Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Cooper Tire & Rubber Company has decided that certain Cooper Discoverer M+S Sport tires fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 571.139 S5.5, "New Pneumatic Radial Tires for Light Vehicles." A non-compliance which relates to motor vehicle safety exists in all tires identified as follows:

<b>Product Name</b>	<b>Size</b>	<b>DOT Serial Number</b>	<b>Brand</b>
COOPER DISCOVERER M+S SPORT	235/75R15	AT 1T CLX 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	255/65R16	AT 3X CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	215/70R16	AT DA CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	225/70R16	AT X5 CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	235/70R16	AT 4E CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	245/70R16	AT 9H CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	265/70R16	AT C2 CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	255/60R17	AT F6 CLW 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	225/65R17	AT 2Y AEK 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	235/65R17	AT 81 CLX 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	265/65R17	AT 2H AEK 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	255/55R18	AT 2T CLX 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	235/60R18	AT 45 AEK 0110-3316	Cooper
COOPER DISCOVERER M+S SPORT	255/50R19	AT LH AEK 0110-3316	Cooper

The following illustration shows the DOT information on a sample of one of the affected tires. DOT sequence begins with AT2TCLX ---- and ends with a date code (2-digit week and 2-digit year) between 0110 and 3316 inclusive, in this example 2516.



Cooper Tire & Rubber Company has determined that the subject tires do not comply with the requirements of 49 CFR 571.139. The subject tires are marked with the Alpine Symbol, but do not meet the traction requirements for snow tires pursuant to the standard. If placed into service, the subject tires may not provide the expected traction or performance in severe snow weather conditions and could potentially increase the risk of a crash.

CTRC1660217

Cooper Tire & Rubber Company is recalling all of the tires with the identification number(s) above. To ensure your safety and satisfaction with our product, we request that you return the recalled tires and this letter to your dealer. If the inspection verifies that you have a tire or tires with the suspect identification number, they will be replaced, mounted and balanced at no charge to you if you have presented them for remedy within sixty (60) days after (i) receipt of this letter or (ii) notice that a replacement tire is available (if not available at the time of inspection). It is expected that replacement tires will be available at the time of the inspection. However, if the tires are not available at the time of inspection, they will be available within twenty-one (21) days. After expiration of the sixty (60) day period, tires will be replaced under our normal adjustment policy.


The time required to determine if the tire is subject to RECALL is only a few minutes and approximately thirty (30) minutes per tire if replacement is required.

Should any questions or problems arise while your tires are being inspected or replaced, please call the Cooper Tire Consumer Relations Department at 800-854-6288. We will attempt to be of service to you. In the event you believe we have failed to or are unable to replace your tire(s) without charge to you, within the sixty (60) day period described above, you may so notify the Secretary of Transportation at the following address: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590, or phone NHTSA's Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153; or go to <http://www.safercar.gov>).

If you've had your tires replaced before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact the Cooper Tire Consumer Relations Department at 800-854-6288.

We regret this inconvenience, but are sure that you understand our interest in your safety and satisfaction with your tires. Please see your dealer immediately for free replacement of the recalled tires. Give this letter to them so that it can be returned to us for purposes of this recall.

Sincerely,



William N. G. Geaman, Jr.  
Manager, Consumer Quality Systems

---

**TO BE COMPLETED BY DEALER**

Tires inspected and replaced \_\_\_\_\_  
(date)

Dealer stamp or name and address:

**Dealer:** Please complete the above section: attach letter to the Manufacturer's Tire Claim Form and return the Claim Form(s) and recalled tire(s) per our standard adjustment procedures.





**COOPERTIRES**

COOPER TIRE & RUBBER COMPANY  
701 Lima Avenue • Findlay, Ohio 45840

**IMPORTANT SAFETY RECALL INFORMATION**

Issued in Accordance  
With Federal Law



U.S. Department of  
Transportation



Sharon Kimball  
PO Box 137  
Bayfield, CO 80112

