

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4819  
URGENT - DISTRIBUTE IMMEDIATELY

Date: August 10, 2018

Subject: 17276-02 - Safety Recall  
Loss of Steering Assist  
Revised Service Procedure section

Models: 2014 Chevrolet Silverado LD  
2014 GMC Sierra LD

To: All General Motors Dealers

This bulletin has been revised to add the following note to the Service Procedure. Note: If the customer states they have experienced a loss of assist or other electrical issues, refer to 18-NA-161 for additional diagnostic and remedy information. Repairs performed in 18-NA-161 are not covered in field action bulletin 17276. Payment for diagnostic and repair work performed in 18-NA-161 is warranty, customer pay or goodwill. Please discard all copies of bulletin 17276-01.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS