

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS4587  
URGENT - DISTRIBUTE IMMEDIATELY

Date: October 12, 2017

Subject: 17376 - Noncompliance Recall  
Incorrect Torsion Bar Built into Front Seat Belt Retractors

Models: 2017-2018 Chevrolet Silverado HD Double Cab  
2017-2018 GMC Sierra HD Double Cab

To: All General Motors Dealers

General Motors is releasing Noncompliance Recall 17376 today. The total number of U.S. vehicles involved is approximately 3,878. Please see the attached bulletin for details.

Vehicles involved in this recall were placed on stop delivery September 14, 2017. Once the service procedure contained in the bulletin has been performed on the vehicle, the vehicle is released from stop delivery and the vehicle can be delivered to the customer.

**Customer Letter Mailing**

The customer letter mailing will begin on October 23, 2017.

**Global Warranty Management (GWM)**

The Investigate Vehicle History (IVH) screen in the GWM system will be updated October 13, 2017. A list of involved vehicles is attached to this message. The involved population consists of Sold vehicles only. Please hold all warranty transactions until the VIN appears in IVH.

END OF MESSAGE

GLOBAL SAFETY FIELD INVESTIGATIONS