



RECALL CAMPAIGN BULLETIN

Reference:

Date:

NTB18-010

February 8, 2018

VOLUNTARY SAFETY RECALL CAMPAIGN 2018 VERSA NOTE; DRIVER AND PASSENGER SIDE CURTAIN AIR BAG MODULES

 CAMPAIGN ID #:
 PM754

 NHTSA #:
 17V-837

 APPLIED VEHICLES:
 2018 Versa NOTE (E12)

Check Service COMM or Dealer Business Systems (DBS) National Service History to confirm campaign eligibility.

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign on certain specific model year 2018 Versa NOTE vehicles to replace the driver and passenger side curtain air bag modules. This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PM754 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

REQUIRED SPECIAL TOOLS

Quick Scan Tool (J-52352) and Panel Popper Tool Set (J-46534)

- Each dealer was previously shipped these tools.
- Additional tools can be obtained from Tech-Mate at 1-800-662-2001.







Figure B

SERVICE PROCEDURE

IMPORTANT: Follow all cautions, warnings, and notes in the Electronic Service Manual (ESM) when working on or near a Supplemental Restraint System (SRS), such as an air bag.

CAUTION: Handle interior trim carefully to avoid damage. Work with clean hands and clean tools to avoid dirt and stains. Use protective covers as needed.

1. Write down the radio settings.

Presets	1	2	3	4	5	6
AM						
FM 1						
FM 2						
SAT 1						
SAT 2						
SAT 3						
Bass	Treb	le B	Balance	Fade	Speed Vol.	Sen.

- 2. Turn the ignition OFF.
- 3. Disconnect both battery cables, negative cable first.
- 4. Wait at least three (3) minutes.

- 5. Remove both new driver and passenger side curtain air bag modules (module) from their packings and register the module numbers as follows:
 - The new modules are listed in the Parts Information.
 - a. Attach the quick scan tool (J-52352) to your CONSULT PC USB port.



Figure 1

b. On the left side of the ASIST main menu, select **Tech Support Info**, and then **Inventory Vehicle Actions**.



Figure 2

c. Select CLICK HERE (AirBag to VIN Registration).

Service Actions -Nissan PC507 2016-17 Titan Diesel TCM Reprogram - Service Action - Dealer Announcement and Procedure CLICK HERE PC502 - 2017 Altima_Maxima Front Member Welds CLICK HERE PC502 - 2017 Altima_Maxima Front Member Welds CLICK HERE PC469 - 2016 Titan Center Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE PC543 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PC640 - 2015 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE Aiveatory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE Select CLICK HERE	NN	A NISSAN Dealer Inventory Action	
PC507 2016-17 Titan Diesel TCM Reprogram - Service Action - Dealer Announcement and Procedure CLICK HERE PC502 - 2017 Altima_Maxima Front Member Welds CLICK HERE PC502 - 2017 Altima_Maxima Front Member Welds CLICK HERE PC469 - 2016 Titan Center Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE PC499 - 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	Service Actions -Nissan		
PC502 - 2017 Altima_Maxima Front Member Welds CLICK HERE PC522 Titan and P6334 Armada ECM Reprogram CLICK HERE PC469 - 2016 Titan Center Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE PC499 - 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PC470, PC549, PC550 Titan Taligate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC507 2016-17 Titan Diesel TCM	Reprogram - Service Action - Dealer Announcement and Procedure CLICK HERE	
PC522 Titan and P6334 Armada ECM Reprogram CLICK HERE PC469 - 2016 Titan Center Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE PC499 - 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PC6466 - 2017 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC502 - 2017 Altima_Maxima Fro	ont Member Welds CLICK HERE	
PC469 - 2016 Titan Center Seat - QAH Dealer Announcement and Repar Procedure CLICK HERE PC499 - 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PM666 - 2017 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC522 Titan and P6334 Armada E	CM Reprogram CLICK HERE	
PC499 - 2017 Rogue Front Camera - Service Action - Dealer Announcement & Procedure CLICK HERE PC543 2017 Rogue TPMS Initialization CLICK HERE PM666 - 2017 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC469 - 2016 Titan Center Seat -	QAH Dealer Announcement and Repar Procedure CLICK HERE	
PC543 2017 Rogue TPMS Initialization CLICK HERE PM666 - 2017 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE Select CLICK HERE	PC499 - 2017 Rogue Front Camer	a - Service Action - Dealer Announcement & Procedure CLICK HERE	
PM666 - 2017 Sentra Accelerator Pedal Inspection CLICK HERE PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC543 2017 Rogue TPMS Initializ	ation CLICK HERE	
PC470, PC549, PC550 Titan Tailgate Lock CLICK HERE R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PM666 - 2017 Sentra Accelerator	Pedal Inspection CLICK HERE	
R1703 2002 Pathfinder Takata Passenger Air Bag Inflator CLICK HERE Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	PC470, PC549, PC550 Titan Tailg	ate Lock CLICK HERE	
Inventory Inspections - Nissan PC482 - ABS Actuator Inspection CLICK HERE Airbag to VIN Registration CLICK HERE Select CLICK HERE	R1703 2002 Pathfinder Takata Pas	isenger Air Bag Inflator CLICK HERE	
		Select CLICK HERE	

Figure 3

- d. Use the quick scan tool to scan the bar code (VIN) on the B-pillar label.
 - Make sure the label is clean.

NOTE:

- Some labels may not scan quickly.
- Hold the scan tool approximately six (6) inches away from the label.
- Hold the trigger down until the label is read (this may take several seconds).



Figure 4

- The VIN will automatically populate (see next page, Figure 5).
- If needed, the VIN can be entered manually.

Please enter/scan the VIN and Airbag Inflator Serial Number Dealer Code Key Number VIN Airbag Serial Number Submit Step f (see next page) Select Submit after bo fields are populated	11/28/2016 1:36:32 1	PM
Dealer Code Key Number VIN Airbag Serial Number Step f (see next page) Select Submit after bo fields are populated	Please enter/scan the VIN and Airba	g Inflator Serial Number
Key Number VIN Airbag Serial Number Step f (see next page) Select Submit after bo fields are populated	Dealer Code	
VIN Airbag Serial Number Step f (see next page) Select Submit after bo fields are populated	Key Number	
Airbag Serial Number Submit Step f (see next page) Select Submit after bo fields are perulated	VIN	
Step f (see next page) Select Submit after bo	Airbag Serial Number	Submit
Step f (see next page) Select Submit after bo		
Select Submit after bo		Step f (see next page)
		Select Submit after both fields are populated

Figure 5

- e. Use the quick scan tool to scan the bar code (serial number) on one of the new modules.
 - The serial number will automatically populate (see Figure 5 on previous page).

NOTE:



Figure 6



Figure 7

f. Select **Submit** on the ASIST screen (see Figure 5 on the previous page).

g. Perform steps 5b-5f on the other new module.

If needed, the serial number can

be entered manually.

DO NOT use the asterisks.

- 6. Replace both driver and passenger side curtain air bag modules with the new ones.
 - Refer to the Electronic Service Manual (ESM), section SR-SRS Airbag, for replacement information.
 - Use Panel Popper Tool Set (J-46534) or equivalent when removing interior trim and parts.
 - See page 2, REQUIRED SPECIAL TOOLS.
- 7. Reconnect both battery cables positive cable first.

- 8. Reset/reinitialize systems as needed.
 - Refer to the ESM, section PG-Power Supply, Ground & Circuit Elements, for a listing of systems that require reset/initialization after reconnecting the 12 V battery.
 - Look in the PG section index for ADDITIONAL SERVICE WHEN REMOVING BATTERY NEGATIVE TERMINAL.
 - This list often includes items such as radio, power windows, clock, sunroof, etc.
- 9. Turn the ignition from OFF to ON and observe the air bag warning light:
 - The air bag warning light should illuminate for seven (7) seconds, and then go out.

NOTE: If the air bag warning light does not operate as described above, there may be an issue not covered by this campaign. Refer to ASIST and the ESM for additional diagnostic and repair information.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
MODULE ASSY-CURTAIN AIR BAG, LH	985P1-9ME8A	1
MODULE ASSY-CURTAIN AIR BAG, RH	985P0-9ME8A	1
GARNISH-CENTER PILLAR, UPPER LH	76914-9ME0A	1
GARNISH-CENTER PILLAR, UPPER RH	76913-9ME0A	1
HEADLINING ASSY (S and Low trim levels)	73910-9ME2A *	
HEADLINING ASSY (SV, SR, and Base trim levels)	73910-9MF3A *	1
BETASEAL 57302N (10.5 oz) **	999MP-57302NP ***	****

* It is recommended to use the VIN in FAST or your electronic parts catalog to determine which Headlining Assembly is needed.

** An equivalent sealant may be used.

***Order BETASEAL 57302N through the Nissan Maintenance Advantage program: Phone: 877-NIS-NMA1 (877-647-6621). Website order via link on dealer portal <u>www.NNAnet.com</u> and click on the "Maintenance Advantage" link.

*****Use **EXPENSE CODE** 101 below for BETASEAL 57302N or equivalent sealant.

NOTE: Return the old/non deployed air bag modules using the <u>Air Bag Module Return</u> <u>Instructions</u> on the next page.

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") I.D.	DESCRIPTION	OP CODE	FRT
PM754	Replace driver and passenger side curtain air bag modules	PM7540	3.0 hrs

EXPENSE CODE

EXPENSE CODE	DESCRIPTION	MAX AMOUNT
101	999MP-57302NP or Equivalent	\$65.00

AIR BAG MODULE RETURN INSTRUCTIONS

NOTE: <u>DO NOT</u> DEPLOY THE USED/NON-DEPLOYED AIR BAG MODULE REMOVED FROM THE VEHICLE.

Returns via YRC Reverse Logistics (for non DDS dealers)

Packaging Instructions

NOTE: Individuals preparing hazardous material ('Hazmat') shipments are required to be trained in accordance with the Code of Federal Regulations, Title 49, section 172.704.

- 1. Place the used/non-deployed air bag module from the vehicle in the carton that the new air bag module was received in. Be sure to package the used module the same way as the new module. Include any packing material that was used to ship the new module in the carton with the used module.
- 2. Seal the carton with 3 inch clear tape across the flaps and along the edges to securely close the carton.
- 3. Verify that the Class 9 hazardous material diamond, UN ID (UN3268), and the proper shipping name (safety devices) are still clearly visible on the carton and are not covered or obstructed in any way.



Required markings:

- 1. Transportation information
- 2. UN specification package markings
- 3. Labels

- 4. ID number
- 5. Proper shipping name
- 4. Write on top of the carton: "Campaign".

Shipping Instructions

NOTE: Please accumulate a minimum of 10-15 air bag modules prior to contacting the YRC Reverse Logistics call center to arrange for the pick-up of the modules.

- 1. Call the YRC Reverse Logistics call center at 1-800-357-9199 and tell the operator that you need to return Campaign air bag modules to your servicing PDC.
- 2. Provide the call center with the name, address and telephone of your servicing PDC.
- 3. Provide your dealership name, address and telephone number.
- 4. Provide the number of air bag modules being returned and the total weight.
- 5. The YRC Reverse Logistics team will fax/email you a copy of the completed Bill of Lading and shipping labels for the shipment.
- 6. The YRC Reverse Logistics call center will notify the local YRC terminal to pick up the air bag modules at your dealership.
 - Please do **NOT** call the local YRC terminal to schedule the pick-up.
- 7. Place the packaged air bag modules and completed Bill of Lading aside for pick up by the carrier.

Returns via DDS

Packing Instructions:

NOTE: Individuals preparing hazardous material ('Hazmat') shipments are required to be trained in accordance with the Code of Federal Regulations, Title 49, section 172.704.

1. Place the used/non-deployed air bag module from the vehicle in the carton that the new air bag module was received in. Be sure to package the used module the same way as the new module. Include any packing material that was used to ship the new module in the carton with the used module.

NOTE: The carton must be in like new condition.

- 2. Seal the carton with 3 inch clear tape across the flaps and along the edges to securely close the carton.
- 3. Verify that the Class 9 hazardous material diamond, UN ID (UN3268), and proper shipping name (safety devices) are still clearly visible on the carton and are not covered or obstructed in any way.



Required markings:

- 1. Transportation information
- 2. UN specification package markings
- 3. Labels

- 4. ID number
- 5. Proper shipping name
- 4. Write on top of the carton "Campaign".

Bill of Lading Instructions (refer to example on the next page):

Use the blank Bill of Lading on page 13 and enter the following:

- 1. Servicing PDC name, address & telephone number.
- 2. Date of the shipment.
- 3. Dealership name and address as indicated on the sample Bill of Lading.
- 4. Number of packages being shipped on line 1.
- 5. Total weight of the packages being shipped on line 1.
- 6. Total number of packages being shipped.
- 7. Total weight of the packages being shipped.
- 8. Print the name of the Hazmat trained/certified employee and have him/her sign as shown on sample Bill of Lading.
- 9. Print the name of the DDS carrier that will be transporting the air bag modules back to your servicing PDC.

Shipping Instructions:

Place the packaged air bag cartons and completed Bill of Lading in DDS delivery area for DDS driver pick up.

SI PLEASE	HIPP NC	FREIGHT CHARGES ARE PREPAID ON THIS BILL OF LADING UNLESS MARKED COLLECT	CARRIER PLEASE NOTE	IF CI	SINGLE SHI HECK BOX	PMENT BELOW	
PLACE PRO LA	BEL HE	RE	DING				
				ORIGI	NAL - NOT		
			DATE (2) P.O. NO.	3111G	SHIPPER NO		
CONSIGNEE (1	O)		SHIPPER (FROM)				
Servici	ng P	DC Name	Dealer Name	3			
street Servicii	ng P	DC Street Address	Dealer Street Addres	s			
CITY, STATE, ZIE	, na P	DC City State and Zin	Dealer City, State and	d Zip			
PHONE NO.	ig i			VEHICLE N	ю.		
Servici	ng P	DC Tel. No.					
NUMBER						WEIGHT (LBS)	
	H	KIND OF PACKAGING DESCRIPTION OF APTICLES	SPECIAL MARKS AND EXCEPTIONS	NMECIN		(Subject to	
	X	AG BOXES X 9 O LBS	SI LOIAL MARKS AND EXCLI HONS	19697	7 55		
(4)-	~			17077		(5)	
		NO PLACARDS REQUIRED PER 49C	FR 1/2.504(F)(9)				
		2016 ERG 171					
4							
(6)	∢ ⊺	OTAL			TOTAL ►	(7)	
EMERGENCY CONTACT: CONTACT MUST BE AVAILABLE 24/7, 365 days per year							
THIS IS TO CERTIFY THAT THE ABOVE NAMED MATERIALS ARE PROPERLY CLASSIFIED, DESCRIBED, PACKAGED, MARKED AND LABELED AND ARE IN PROPER CONDITION FOR TRANSPORT ACCORDING TO THE APPLICABLE REGULATIONS OF THE DEPARTMENT OF TRANSPORTATION.							
SHIPPER			CARRIER		(9	
Hazma	t Trc	iined Person	DDS Carrier Name				
AUTHORIZED S	IGNATU	RE 8	AUTHORIZED SIGNATURE	DATE	0/17		
Hazma	TIC	linea Person's Signature	Carrier Driver Signature	04/1	2/17		
				NUMBER (OF PIECES REC		

SHIPPER PREIGHT CHARGES ARE PREPAID ON THIS BILL OF LADING UNLESS MARKED COLLECT				PLE	CARRIER IF SINGLE SHIPMENT PLEASE NOTE CHECK BOX BELOW					
PLACE PRO LABEL HERE				STRAIGHT	STRAIGHT BILL OF LADING ORIGINAL - NOT NEGOTIABLE					
					DATE	P.O. NO.			SHIPPER NO	D
CONSIGNEE (1	fO)				SHIPPER (FROM)	1				
STREET					STREET					
CITY, STATE, ZI	P				CITY, STATE, ZIP					
PHONE NO.				ROUTE			VEHIC	CLE NO.		
NUMBER SHIPPING UNITS	H M	KIND OI	FPACKAC	GING, DESCRIPTION OF ARTICLES	, SPECIAL MARKS AN	D EXCEPTIONS	NMF	C No.	CLASS	WEIGHT (LBS) (Subject to Correction)
	47	ΟΤΑΙ						TC		
	- 1									
THIS IS T MARKED REGULAT		ERTIFY D LABEI	THAT TH ED AN	IE ABOVE NAMED MATER D ARE IN PROPER COND TMENT OF TRANSPORTATIO	RIALS ARE PROP DITION FOR TRAI	ERLY CLASSI NSPORT ACC	FIED, Cord	DESC	CRIBED, TO THE	PACKAGED, APPLICABLE
SHIPPER					CARRIER					
AUTHORIZED S	IGNATU	RE			AUTHORIZED SIGNATURE		DATE			
	NUMBER OF PIECES RECEIVED ▲									