

CONDITION OF CONCERN

In the subject vehicles, continued exposure to high levels of absolute humidity may cause the driver's and/or passenger's frontal air bag inflator to explode in the event of a crash. **An air bag inflator explosion could result in metal fragments striking the driver or other vehicle occupants, resulting in serious injury or death.** It is **extremely important to schedule this repair as soon as possible, to ensure your safety and the safety of your passengers.**

The vehicle may have had temporary air bag inflators installed under Safety Recalls 9116A and/or 8315F. However, both the driver and passenger PERMANENT remedy inflators must be replaced on all customer vehicles at the same time.

These are the same vehicles subject to Safety Recall 1917L.

SUBJECT VEHICLES

Model	VIN range	Build Date Range
2004-2006 B-Series Truck	ALL (except vehicles included in 2318A)	April 17, 2003 through May 2, 2006

MANDATORY AIR BAG INFLATOR RETURN

All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MGSS and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

OWNER NOTIFICATION

Mazda will notify U.S. owners beginning January 17, 2018.

PARTS INFORMATION

A web page to order parts for this recall is available in MXConnect. A complete VIN is needed to process the order.

Description	Part Number	Quantity	Notes
Passenger Frontal Air Bag Inflator	1FT1-57-K50A	1	Permanent Repair
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

WARRANTY CLAIM PROCESSING INFORMATION

Recall 1817L – PAB “Permanent” Repair	Replacement of Passenger Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1802A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K50A / 1 pc
Labor Operation Number	YY793XRX
Labor Hours	0.7 hrs.

RENTAL CAR INFORMATION

PLEASE CLAIM ANY RENTALS ON RECALL 1917L