

Part 573 Safety Recall Report

18E-005

Manufacturer Name : FUEL HELMETS

Submission Date : JAN 24, 2018

NHTSA Recall No. : 18E-005

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : FUEL HELMETS

Address : 1819 SAINT GEORGE STREET
GREEN BAY WI 54302

Company phone : 8553553835

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Equipment Information :

Brand / Trade 1 : FUEL HELMETS

Model : SH-HHGL1

Part No. : SH-HHGL14

Size : SMALL

Function : NR

Descriptive Information : We are currently looking in to this matter to provide an accurate response.

Production Dates : JAN 01, 2018 - JAN 02, 2018

Description of Defect :

Description of the Defect : RETENTION STRAP FAIL - LOW & HIGH TEMPATURE

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The retention test failed DOT Lab testing. we are currently investigating to provide an accurate response.

Description of the Cause : NR

Identification of Any Warning that can Occur : We are reviewing and currently investigating to provide an accurate response.

Supplier Identification :

Component Manufacturer

Name : Zhejiang Bio Industrial & Trade Co., Ltd

Address : 1269 QiuBin Distric

Jinhua City FOREIGN STATES 321016
Country : China

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs
from Recalled Component : NRIdentify How/When Recall Condition
was Corrected in Production : NR**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name : Fuel Helmets

Address : 1819 Saint George Street
Green Bay WI 54302

Country : US

Company Phone : 9202423700

* NR - Not Reported