



July 4th, 2018

[REDACTED]

Dear customer,

Your vehicle (1NPTX4E [REDACTED]) is part of a recall by Transport Canada # 2018308. A plastic insulation, also called wheel guard, built by FleetSpec, has been installed between the wheel and the brake drum, or between the wheel hub and the wheel to prevent corrosion between both components of your truck. This piece has been installed on front twin steer axle or front tridem steer axle vehicles modified by Simard Suspensions between March 1st and November 30th 2017.

These FleetSpec wheel guards may melt because of the heat generated by the brakes. In this case, a wheel could loosen and fall from the vehicle. Simard Suspensions requires that you remove these Fleetspec wheel guards. If you wish to replace them, we recommend the Accuride wheel guards, part number 5903. Please contact Simard Suspensions to confirm the number of wheel guards needed. They will be shipped free of charge.

Simard Suspensions also offers a compensation of 150\$ to take off or replace wheel guards. We invite you to send a bill to Simard Suspensions, 1064 Boulevard Monseigneur de Laval, Baie-St-Paul, Québec, G3Z 2W9 showing VIN and the following information:

- Reference Transport Canada # 2018308;
- Repair date;
- Truck mileage;
- Either options :
 1. Take off the wheel guards;
 2. Replace the wheel guards.

Simard Suspensions Inc. will pay the bills by check according to the order of reception.

For any question, please contact Simard Suspensions service department via:

Email : service@simardsuspensions.com or call our dedicated phone number: 1-877-898-8317

A handwritten signature in blue ink, appearing to read 'D. Tremblay', is placed above the name and title.

David Tremblay
President