

## IMPORTANT UPDATE

### TECHNICAL INSTRUCTIONS FOR SAFETY RECALL H0A FRONT PASSENGER AIRBAG INFLATOR CERTAIN 2008 - 2009 MY SCION xB

**UPDATED 4-18-18**

**Update 4-18-18**

- The parts section has been updated

**Update 2-6-18**

- Updated parts information for clip kits

**Update 1-9-18**

- Added 2009 MY


The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Toyota Expert (Electrical)
- Master
- Master Diagnostic Technicians

Always check which technicians can perform the recall remedy by logging on to <https://www.uotdealerreports.com>. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.


## I. OPERATION FLOW CHART

The flow chart is for reference only. **DO NOT** use it in place of the full technical instructions. Follow **ALL** steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



## II. BACKGROUND

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. According to Takata, the propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause inflator rupture during airbag deployment. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.



### III. IDENTIFICATION OF AFFECTED VEHICLES

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- **TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.**

### IV. PREPARATION

#### A. PARTS

Part Number	Part Description	Quantity
04007-06812	Instrument Panel Airbag Inflator Kit*	1
* The kit above includes the following parts.		
Part Number	Part Description	Quantity
-	Inflator	1
-	Self-locking Nut	5
-	Position Determining Plate	1

Part Number	Part Description	Quantity
04006-66108	Clip Kit*	1
* The kit above includes the following parts.		
Part Number	Part Description	Quantity
-	Front Pillar Garnish Clip	2

**OR**

Model	Part Number	Part Description	Quantity
Scion xB	04006-49312	Instrument Panel Airbag Module (Instructions for this part are in the module replacement TI)	1
	04006-66108	Clip Kit*	1
* The kit above includes the following parts.			
	Part Number	Part Description	Quantity
		Front Pillar Garnish Clip	2

**IF USING THE PART MENTIONED ABOVE, FOLLOW THE INSTRUCTIONS IN THE MODULE REPLACEMENT TI**

#### Non-Desiccated Part Recovery

**Dealers should discontinue the installation of the non-desiccated parts listed below for recall, customer pay repairs AND over-the-counter sales (if applicable).**

Model	Model Year	Part Number	Part Description
Scion xB	2008-2013	73970-12140	AIR BAG ASSY, INSTR PNL PASS

**Toyota requires all dealers to return any parts listed above that still remain in dealer inventory by utilizing the Hazmat Part Return Program available. Dealers will be issued a refund for all part returns. This part return program is outlined in *PANT Bulletin 2014-042*.**

#### Important Note:

In order to return the inflator, packages must **NOT** be opened/tampered with.


## A. TOOLS & EQUIPMENT

- Standard hand tools
- Torque wrench
- Techstream
- Molding remover set



## B. MATERIALS

- Protective Tape
- Marker Pen

**G0P/G0R/H0A CAMPAIGN TOOLS** – These tools were previously provided to the dealership for campaign F0J and will be used for this campaign. These tools are required when performing this repair.

Image	Name	Quantity
	Barcode Scanner (The scanner distributed for F0J can read bar and QR codes)	1

**NOTE:** This tool **CANNOT** be ordered through the parts or tools system. If additional tools are needed, they can be sourced locally.

Image	Name	Quantity
	Airbag Mounting Bracket & hardware (Provided to the dealership at the launch of SSC DLC)	1
	579943 Adaptor set*	1

\*The adapter set was sent to dealers prior to the start of this campaign.

**SST** –These are essential service tools that the dealership should have.

<b>Part Number</b>	<b>Part Name</b>	<b>Quantity</b>
09950-50013	Puller C Set *	1
* The set above includes the following tools.		
<b>Part Number</b>	<b>Part Name</b>	<b>Quantity</b>
09951-05010	Hanger 150	1
09952-05010	Slide Arm	2
09953-05020	Center Bolt 150	1
09954-05021	Claw No. 2	2

## V. SAFETY PRECAUTIONS



### CRITICAL INFORMATION – READ THOROUGHLY



Failure to follow these procedures correctly could cause the SRS to unexpectedly deploy during servicing or the SRS may fail to operate correctly when required after reassembly. Confirm all work is performed as described in these instructions.

DO NOT CONNECT PREMATURELY  
CANNOT DISCONNECTED

**NG**




R170128000


1. **IMPORTANT NOTICE WHEN CONNECTING INSTRUMENT PANEL WIRE CONNECTOR TO AIRBAG INFLATOR**
  - a) Once connected, the instrument panel wire connector cannot be disconnected from the airbag inflator. If the instrument panel wire connector is incorrectly connected to the inflator, replace the instrument panel wire and inflator with new ones.

2. **ELIMINATE STATIC ELECTRICITY**

- a) Before starting work and periodically while working on the vehicle, touch a metallic part of the vehicle to discharge static electricity in the body.



**NG** DO NOT  
measure resistance.




R1508210026

3. **DO NOT MEASURE RESISTANCE**

- a) **DO NOT** measure resistance of airbag components, this may cause accidental activation.

**NG** Replace with  
new one.




R1508210027

4. **HANDLE THE AIRBAG CAREFULLY**

- a) If an airbag is dropped, replace it with a **NEW** one.

5. **WEAR PROTECTIVE EQUIPMENT**

- a) Always wear appropriate protective equipment when working on the SRS.



Wear protective eye wear  
and work gloves.

## VI. SRS SYSTEM HEALTH CHECK

### 1. PERFORM A HEALTH CHECK

- Confirm the Techstream is connected to the dealership's internet.
- When launching the Techstream software the VIN may need to be entered manually.

**NOTE: All letters of the VIN *MUST* be entered in ALL CAPS, or the VIN will need to be reentered when running the diagnostic report.**

- Perform a health check.

**Note: The VIN may auto populate on the later model year vehicles, if this happens DO NOT change the VIN.**

### 2. RUN A DIAGNOSTIC REPORT

- After the health check has completed, run a diagnostic report by clicking on the link on the health check screen.

**NOTE: If the VIN was not entered in ALL CAPS when Techstream was launched, an error will be displayed and there will be a prompt to reenter the VIN**



- Enter the vehicle mileage and repair order information, then click the 'report' button.




- The VIN **MAY NEED** to be entered manually in ALL CAPS when launching the Techstream software. The VIN should auto-populate on 2006 and later MY vehicles.
- A health check and diagnostic report with VIN **MUST** be performed within the last 36 hours and recorded by TMS. If the diagnostic report is not run, the healthcheck will not be recognized by TMS.
- The serial number recording application will be disabled and the repair cannot be completed if a health check and diagnostic report is not performed and recorded by TMS.
- This campaign only covers the replacement of the passenger airbag module. NO other SRS components are covered under this campaign.



## VII. PASSENGER AIRBAG MODULE REPLACEMENT

### COMPONENTS




**N\*m (kgf\*cm, ft.\*lbf)** : Specified torque

R1612150001



**3.9 N·m (40, 35 in.\*lbf)**  
**Be careful not to**  
**overtighten.**



R1707250002

## 1. REMOVE THE AIRBAG MODULE


a) Refer to TIS for instructions on airbag removal:

[2008 MY](#) [2009 MY](#)



- Wait at least 90 seconds after disconnecting the cable from the negative battery terminal to prevent airbag and seat belt pre-tensioner deployment.
- Follow all precautions as outlined on TIS before servicing the SRS system.

## 2. REMOVE INFLATOR FROM THE AIRBAG MODULE



### 1. REMOVE THE INFLATOR

- a) Mark the 5 self locking nuts to prevent reuse.




- a) Mount the adaptors (579943-3R3) to the airbag as shown.

**NOTE: The 6mm stud mounts to the airbag.**




- b) Mount the airbag to the mounting bracket as shown.




- c) Loosen the 5 nuts until each nut is flush with the top of the stud as shown.

**NOTE:** You may need to slide the airbag to the left or right to access the middle nut.  
**DO NOT** use power tools to remove the nuts.




- d) Loosen and discard the 2 nuts on the end where the positioning plate is removeable.  
e) Remove and discard the plate.

**NOTE:**  
**DO NOT** use power tools.



- f) Remove the inflator.

- g) Mark the old inflator so it is not reused.  
**NOTE: Return the old inflator to the parts department for recovery.**



### 3. LAUNCH THE SERIAL NUMBER RECORDING APPLICATION



- The **AIRBAG MODULE** serial number **MUST** be recorded using the barcode scanner (provided at the launch of SSC F0J).
- The barcode scanner application **MUST** be completed on every vehicle. These numbers **MUST** be included on every warranty claim that is submitted for module replacement or the claim may be subject to debit.
- The technician performing the work **MUST** have valid TIS login credentials and an internet connection to perform the inspection and scanning process.

- Log in to TIS and input the VIN of the vehicle in the Vehicle Inquiry tab.
- Confirm the VIN is applicable and that the campaign has not been completed.
- Click on the link to launch the serial number recording application.

**Note:** The Serial Number Recording Application is the same as the previous application, so the screens will still indicate an older campaign.

Vehicle Identification Number Search

Enter a 17-Digit VIN below to search for applicable information:

VIN: 1NX-BR32E-000000000

**a)**

**Vehicle Information**

Division: TOYOTA	Model: Corolla	Grade: CE	Model Year: 2003
Drive Type: 2WD	Body Type: 4Dr. Sedan	Engine Family: 4-cylinder - 1ZZ	Transmission:
Date of First Use:	Production Date: 01/18/2002	Plant Code: Z - FREMONT PLANT - NUMMI	
VIN: 1NX-BR32E-000000000		Standard Equipment: <a href="#">Click here to display</a>	
Exterior Color: 03M5, SANDRIFT METALLIC		Interior Color: FA41, FA41	Interior Trim Color: FA, *
Interior Fabric: F, *			

Vehicle accessories are not currently available. Try your query again later.

**Service Campaign**

Campaign Description: Safety Recall DCF Remedy Notice - 2003-2004 Model Year Corolla, Corolla Matrix, Sequoia, and Tundra Vehicles, 2002-2003 Model Year Vehicles Front Passenger Airbag Inflator Module

Completion Status: **Not Completed** **b)** [Check applicability for VIN](#) **c)**

[Show Documents]

© 2013 Toyota Motor Sales, Inc. Feedback | Privacy | Legal

- Reenter TIS password in the serial number recorder application.

**NOTE:** The person logged-in to TIS **MUST** be the person performing the repair.

Front Passenger Airbag Inflator Module - Safety Recall

SSC - DSF

User ID: Suzuki  
Dealer Code:  
Time: 06/10/2014 02:07 PM PDT  
Original Inflator Serial #:

Technician Name: Russell Suzuki  
Airbag Serial #:  
Replacement Inflator Serial #:

VIN: 1NX-BR32E-000000000 **a)**

Task	Dealer	User	Time	Status
Airbag # Record				Not Started
Inflator # Record				Not Started
Check & Conditions				Not Started
Scan Airbag #				Not Started

- Record the vehicle mileage into the serial number recording application.

**NOTE:**

- If this screen indicates that the module has already been replaced on this VIN, there is no need to perform the campaign again.

#### 4. CONNECT THE BARCODE SCANNER

- Connect the barcode scanner to the USB port on the Techstream.
- The scanner will automatically connect and a beep will be heard when the scanner is ready.

##### NOTE:

- The scanner was provided for SSC F0J.
- The scanner works best in low light conditions.
- Always hold the scanner directly in front of and parallel to the barcode label.

#### 5. SCAN THE AIRBAG SERIAL NUMBER

- Scan the **AIRBAG ASSEMBLY** serial number 2 times.
  - Confirm that the cursor is in the first serial number box then scan the bar code.
  - Position the cursor in the second serial number box and rescan the bar code.

- Click next.

##### NOTE:

- If both the serial numbers do not match, confirm and reenter.
- If the serial number barcode will not scan, it can be entered manually.

#### AIRBAG SERIAL NUMBER IDENTIFICATION

- The airbag serial number is **ALWAYS** the 12 **DIGITS** located between the asterisks.
- The 3 digits before the asterisk **ARE NOT** part of the serial number, and **SHOULD NOT** be entered or an inaccurate response may be returned.

##### Airbag Serial Number Label Example



STOP

The **AIRBAG** serial number **MUST** be recorded prior to replacement.

Front Passenger Airbag Inflator Module - Safety Recall  
SSC - E04

User ID: Technician Name:  
Dealer Code: Dealer Name:  
Time: 03/30/2015 05:15 AM PDT VIN: 1 2004 Corolla SUPER WHITE]

How to Identify an Airbag module Assembly number?

The Airbag module Assembly serial number is a 12 digit code. It can be found along with a bar code on opening the Airbag assembly unit. To manually enter these details into the application, the technician has to identify the 12 digit code between two Asterisks (\*) inside the Airbag assembly unit. The first seven characters of this 12 digit code are numbers and the 10<sup>th</sup> digit is either 'K' or 'L' always.

Original Airbag Module - 12 Digits Between the asterisk (\*) symbols

Record Airbag Serial Number

Use of a barcode scanner is strongly recommended when entering Airbag Assembly Serial Number.

If manually typing serial number, you MUST include all leading zeros. (If applicable)

\* Airbag Assembly Serial Number:   
\* Reconfirm Airbag Assembly Serial Number:

If original Airbag Assembly serial number is not visible or missing, check this box: ☐

(\*) - Indicates Required Field(s)

Next



## Front Passenger Airbag Inflator Module - Safety Recall

SSC - E04

1 2 3 4

User ID:

Dealer Code:

Time: 03/30/2015 05:17 AM PDT

VIN:


2004 Corolla SUPER WHITE]

Technician Name:

Dealer Name:

Airbag Serial #: \*\*\*\*\*12

### Original Inflator



How to Identify the Inflator serial code on the Original and Replacement Inflator can?

The Inflator serial code is an **11 digit code** on the Inflator can. It can be found with a bar code on removing the Inflator can from the Airbag Assembly unit.

The first two characters of the **Original Inflator Serial code** will be from [AA, AB, AJ, FD or JD].

The first two characters of the **Replacement Inflator Serial code** will be either 'LT' or 'LR'.

### Replacement Inflator



Inflator Module replacement IS REQUIRED on all vehicles under the Safety Recall. Follow the technical instructions and acknowledge the following statements.

**If manually typing serial number, you MUST include all leading zeros. (If applicable)**

Original Inflator Serial #:

If old inflator serial number is not visible or missing, check this box. ☐

Replacement Inflator Serial #:

**If you have a concern with the inflator serial numbers, please email [quality\\_compliance@toyota.com](mailto:quality_compliance@toyota.com) with details.**

- ☐ I agree to complete the safety recall's remaining technical instructions.
- ☐ I agree to perform a vehicle Health Check with Techstream upon completion of the safety recall's technical instructions.

(\*) - Indicates Required Field(s)

Back Clear **Sub**

c) Confirm agreement by checking the two boxes and press submit.



d) Record the Warranty Authorization # to be included in the warranty claim.

T3 :: SuzukiR - Google Chrome  
t3qa.tms.toyota.com/t3Portal/portlets/tis/airBag/AirBagController.portlet?\_nfpb=true&\_windowLabel=Standal

## Front Passenger Airbag Inflator Module - Safety Recall

### SSC - DSF

1 2 3 4 5

**User ID:** SuzukiR  
**Dealer Code:**  
**Time:** 06/10/2014 05:13 PM PDT  
**Original Inflator Serial #:** AAEL5110212

**Technician Name:** Russell Suzuki  
**Dealer Name:**  
**Airbag Serial #:** \*\*\*\*\*96  
**Replacement Inflator Serial #:** AAEL5110213

SuzukiR has agreed to the following terms and conditions on 06/10/2014 05:13 PM PDT

- ☒ \* I agree to complete the safety recall's remaining technical instructions.
- ☒ \* I agree to perform a vehicle Health Check with Techstream upon completion of the safety recall's technical instructions.

**Russell Suzuki** has successfully confirmed completion of Airbag Inflator Module Safety Recall for

**VIN -** [2003 Sequoia BEIGE M. M.]

**Warranty Authorization #: b5511e9f**

Airbag inflator module was replaced under this safety recall.

Print this page for your records and then click 'Close' to resume working.

Close

e) Confirm agreement by checking the two boxes.

f) Place the old airbag in the parts box and return it to the parts department.

**NOTE:**

- Keep all shipping paperwork with the box that it came in.
- Confirm the cursor is in the correct serial number input box before scanning.
- If the serial number barcode will not scan, it can be entered manually.
- If there are any difficulties or concerns with this process, email [quality\\_compliance@toyota.com](mailto:quality_compliance@toyota.com) with details.

## AIRBAG SERIAL NUMBER IS MISSING OR IS UNREADABLE



If the airbag serial number and barcode are not legible or are not present, check the box in the application indicating the serial number is not legible.

a) If the airbag serial number cannot be scanned or is not present check the box as shown below.

Front Passenger Airbag Inflator Module - Safety Recall


**SSC DSC**

1 2 3 4 5

User ID: Technician Name:

Dealer Code: Dealer Name:

Time: 03/30/2015 05:15 AM PDT VIN: [2004 Corolla SUPER WHITE]



Original Airbag Module - 12 Digits  
Between the asterisk (\*) symbols

How to Identify an Airbag module Assembly number?

The Airbag module Assembly serial number is a 12 digit code. It can be found along with a bar code on opening the Airbag assembly unit. To manually enter these details into the application, the technician has to identify the 12 digit code between two Asterisks (\*) inside the Airbag assembly unit. The first seven characters of this 12 digit code are numbers and the 10<sup>th</sup> digit is either 'K' or 'L' always.

Record Airbag Serial Number

Use of a barcode scanner is strongly recommended when entering Airbag Assembly Serial Number.

If manually typing serial number, you MUST include all leading zeros. (If applicable)

\* Airbag Assembly Serial Number:

\* Reconfirm Airbag Assembly Serial Number:

If original Airbag Assembly serial number is not visible or missing, check this box ☐

(\*) - Indicates Required Field(s)

Clear Next

**Check this box if the Airbag serial number is not legible.**  
**Note: Contact your area office in the event you are unable to read the serial number**  
**DO NOT ATTEMPT TO INSTALL THE INFLATOR**

- b) After the Area office approves the Airbag replacement and the new part is received, scan the new Airbag barcode in the Serial Number Recording Application.


## Front Passenger Airbag Inflator Module - Safety Recall

### SSC DSC

12345

User ID:  
Dealer Code:  
Time: 03/30/2015 05:15 AM PDT

Technician Name:  
Dealer Name:  
VIN: 2004 Corolla SUPER WHITE]



Original Airbag Module - 12 Digits  
Between the asterisk (\*) symbols

#### How to Identify an Airbag module Assembly number?

The Airbag module Assembly serial number is a **12 digit code**. It can be found along with a bar code on opening the Airbag assembly unit. To manually enter these details into the application, the technician has to identify the 12 digit code between two Asterisks (\*) inside the Airbag assembly unit. The first seven characters of this 12 digit code are numbers and the 10<sup>th</sup> digit is either 'K' or 'L' always.

Record Airbag Serial Number

Use of a barcode scanner is strongly recommended when entering Airbag Assembly Serial Number.

If manually typing serial number, you **MUST** include all leading zeros. (If applicable)

\*New Airbag Assembly Serial Number:

☐ I agree to complete the safety recall's remaining technical instructions.

☐ I agree to perform a vehicle Health Check with Techstream upon completion of the safety recall's technical instructions.

(\*) - Indicates Required Field(s)

Next

- c) Confirm agreement by checking the two boxes and press next to advance to the Warranty authorization screen.
- d) Return the old airbag to the parts department.
- e) Proceed to Section IX Step 2.



The new **AIRBAG ASSEMBLY** serial number **MUST** be recorded prior to reinstallation to track the airbag assembly to the vehicle.

## VIII. FRONT PASSENGER AIRBAG REINSTALLATION

### 1. INSTALL A NEW INFLATOR




Make sure to follow the installation procedure carefully as the instrument panel wire connector cannot be disconnected once connected.

- a) Insert a **NEW** inflator to the center of the airbag case with the correct orientation as shown in the illustration.




- Make sure that the passenger airbag inflator is oriented correctly as shown in the illustration, not upside down.
- If the passenger airbag inflator is upside down, it will not be able to be fully inserted.



- b) Connect the airbag connector to the instrument panel passenger airbag assembly and then push in the airbag connector lock as shown in the illustration.




- Make sure to correctly align the connectors before connecting them.
- Make sure that the airbag connector is securely connected.



c) Insert the inflator fully as shown in the illustration.




**DO NOT pinch instrument panel wire.**




d) Insert the inflator with the correct orientation as shown in the illustration.



- Make sure that the inflator is oriented correctly as shown in the illustration, not upside down.
- If the passenger airbag inflator is upside down, it will not be able to be fully inserted.




Install temporarily  
by hand.



e) Temporarily install a **NEW** plate and airbag inflator with the 2 **NEW** self-locking nuts.

Install temporarily  
by hand.



- f) Remove the 3 remaining old self-locking nuts and install temporarily 3 **NEW** self-locking nuts by hand.
- g) Store the removed self-locking nut in a replacement part box or the like.



h) Push the inflator and plate to towards the position determining plate to eliminate any gap.



**If any gap exists, the aligned flats may move apart, resulting in failure in normal deployment of the airbag.**


- i) Tighten 5 nuts evenly in several increments in the order shown in the illustration using a socket driver while pushing the inflator and plate. (You will encounter some resistance during tightening because these nuts are self-locking nuts.)

**Torque: 3.9 N·m (40 kgf·cm, 35 in.\*lbf)**



**The tightening torque is low (3.9 N·m). Use of an air ratchet wrench or tightening strongly with a T-handle wrench or a ratchet handle may cause deformation of the stud bolt.**


**OK**




**NG**

**NG**


**NG**



**Too Tight!**



**Too Tight!**




**These tools cause overtightening !**

R1707250013

## 2. INTERMEDIATE INSPECTION

- a) Check that the inflator and the 5 self-locking nuts, instrument panel wire are replaced.
- b) Check that positions of the inflator and the position determining plate are correct.  
(There should be no gap.)



R1707250014

## 1. REINSTALL THE AIRBAG MODULE

- a) Refer to TIS for instructions on airbag installation:

[2008 MY](#) [2009 MY](#)

## 2. RECONNECT THE NEGATIVE BATTERY CABLE

- a) Reconnect the negative battery cable.
- b) Perform any needed system initializations.

## 3. PREFORM ANY NEEDED VEHICLE INITIALIZATIONS

## 4. PERFORM A HEALTH CHECK AND DIAGNOSTIC REPORT




## ◀ VERIFY REPAIR QUALITY ▶

- Confirm all precautions are followed to ensure safety during the repair
- Confirm the entire serial number checker application is completed and the warranty authorization # is recorded on **EVERY** vehicle
- Confirm the old inflator is handled safely and given to the appropriate parts professional for shipment

If you have any questions regarding this update, please contact your regional representative.

## IX APPENDIX

### A. CAMPAIGN DESIGNATION DECODER



Examples:

A0D = Launched in 2010, Remedy Phase, 4<sup>th</sup> Campaign Launched in 2010

B1E = Launched in 2011, Interim Phase, 5<sup>th</sup> Campaign Launched in 2011

C1C = Launched in 2012, Interim Phase, 3<sup>rd</sup> Campaign Launched in 2012

### B. CAMPAIGN PARTS DISPOSAL

**ALL** inflators that are removed from vehicles under this campaign **MUST** be packaged and shipped back to the inflator manufacturer following the manufacturer's instructions. The instructions can be found in the following locations:

- Attached to the dealer letter
- Included in the parts box