

CONDITION OF CONCERN

The passenger side air bag inflator (recall 2318A) in this vehicle **must** be repaired at the same time as the driver side air bag inflator. Note: The driver side airbag inflator in your vehicle may be part of a small population of inflators that pose a higher risk of **explosion** in the event of a crash that causes an air bag deployment. Two inflators built at Takata on the same day as the driver side air bag inflator in your vehicle have **exploded** causing fatal injuries. **An inflator explosion could result in sharp metal fragments striking the driver or other vehicle occupants, resulting in SERIOUS INJURY OR DEATH.**

These are the same vehicles subject to Safety Recall 2218A.

SUBJECT VEHICLES

Model	VIN range	Build Date Range
2006 B-Series Truck	Varies – 143 vehicles – see MGSS for VIN's	Vehicles with a specific B-Series Takata air bag manufactured between September 3, 2005 and September 5, 2005

MANDATORY AIR BAG INFLATOR RETURN

All inflator part numbers can be counted and shipped together for these returns. To schedule a return, please contact XPO at (877) 650-3476. Detailed air bag inflator return instructions are provided in Attachment IV, and can also be found on MGSS and the Dealer Assistance Group website. Failure to return the original inflator will result in a Warranty Claim Debit.

OWNER NOTIFICATION

Mazda will notify U.S. owners by overnight and certified mail (2 mailings) beginning January 18, 2018.

PARTS INFORMATION

A web page to order parts for this recall is available in MXConnect. A complete VIN is needed to process the order.

Description	Part Number	Quantity	Notes
Passenger Frontal Air Bag Inflator	1FT1-57-K50A	1	Permanent Repair
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)

WARRANTY CLAIM PROCESSING INFORMATION

Recall 2318A – PAB “Permanent” Repair **CRITICAL**	Replacement of Passenger Frontal Air Bag Inflator
Applicable Model	B-Series
Warranty Type	R
Process Number	J1804A
Symptom Code	99
Damage Code	99
Part Number Main Cause & Quantity	1FT1-57-K50A / 1 pc
Labor Operation Number	YY795XRX
Labor Hours	0.7 hrs.

RENTAL CAR INFORMATION

PLEASE CLAIM ANY RENTALS ON RECALL 2218A