OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

18V-046

Manufacturer Name: Ford Motor Company

Submission Date: FEB 11, 2019 NHTSA Recall No.: 18V-046 Manufacturer Recall No.: 18S01



Manufacturer Information:

Manufacturer Name: Ford Motor Company

Address: 330 Town Center Drive

Suite 500 Dearborn MI 48126-2738

Company phone: 1-866-436-7332

Population:

Number of potentially involved: 327,796 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2009-2010 Ford Ranger

Vehicle Type: LIGHT VEHICLES

Body Style: Power Train: NR

Descriptive Information: The vehicles, model years, and geographic locations affected by this recall have been

identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015

Consent Order in EA15-001.

Ford Motor Company (Ford) is conducting a safety recall in accordance with the May 3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years

affected for each zone are provided in a separate attachment.

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service

Information System (OASIS) database.

Production Dates: MAY 27, 2008 - JUN 26, 2010

VIN Range 1 : Begin : NR End: NR

Vehicle 2: 2009-2010 Ford Fusion

Vehicle Type: LIGHT VEHICLES

Body Style: Power Train: NR

Descriptive Information: The vehicles, model years, and geographic locations affected by this recall have been

identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015

Consent Order in EA15-001.

Ford Motor Company (Ford) is conducting a safety recall in accordance with the May

	3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment.								
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.								
Production Dates	FFR 18 2008 - I	FEB 18, 2008 - JUL 25, 2010							
VIN Range 1		NR	End: NR	☐ Not sequential					
Vehicle 3: 2009-2010 Mercury Milan Vehicle Type: LIGHT VEHICLES Body Style: Power Train: NR Descriptive Information: The vehicles, model years, and geographic locations affected by this recall have bee identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001. Ford Motor Company (Ford) is conducting a safety recall in accordance with the Ma 3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtat specific information regarding the vehicles from the Ford On-line Automotive Servi Information System (OASIS) database.									
Production Dates VIN Range 1	: FEB 19, 2008 - JUL 24, 2010 : Begin : NR End : NR ☐ Not sequential								
	-0	-							
		J							
	The vehicles, model years, and geographic locations affected by this recall have been identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.								

Ford Motor Company (Ford) is conducting a safety recall in accordance with the May 3, 2016 Amendment to the Consent Order for vehicle models listed and originally

		delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service							
		Information System (OASIS) database.							
	Production Dates : VIN Range 1 :		AN 24, 2013 NR	End:	NR	☐ Not sequential			
		2009-2010 Ford LIGHT VEHICLE NR	· ·						
		n: The vehicles, model years, and geographic locations affected by this recall have been identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.							
		Ford Motor Company (Ford) is conducting a safety recall in accordance with the May 3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment.							
		These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.							
	Production Dates : VIN Range 1 :		UL 01, 2010 NR	End:	NR	☐ Not sequential			
		2009-2010 Lind LIGHT VEHICLE							
Descriptive Information : The vehicles, model years, and geographic locations affected by this recall identified as prescribed in the May 3, 2016 Amendment to the November Consent Order in EA15-001.									
						recall in accordance with the May e models listed and originally			

delivered or ever-registered in the Zones A, B, and C. The vehicles and model years

	affected for each zone are provided in a separate attachment.								
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.								
Production Dates:	: JUN 16, 2008 - JUL 12, 2010								
VIN Range 1:		NR	End:	NR	☐ Not sequential				
- VIIV Runge 1.	Degin .	1410	Life.		not sequential				
Vehicle 7:	: 2009-2010 Ford Mustang								
Vehicle Type :	LIGHT VEHICLE	S							
Body Style :									
Power Train :									
Descriptive Information :	The vehicles, model years, and geographic locations affected by this recall have been identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.								
	Ford Motor Company (Ford) is conducting a safety recall in accordance with the May 3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment.								
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.								
	FED 07 0000 A	MAD 07 0010							
Production Dates :		NR	End:	MD	□ Not coquential				
VIN Range 1:	begin.	NK	Ena .		☐ Not sequential				
Vehicle 8:	2009-2010 Linc	oln MKZ							
Vehicle Type :	: LIGHT VEHICLES								
Body Style :									
Power Train :	NR								
Descriptive Information :	: The vehicles, model years, and geographic locations affected by this recall have been identified as prescribed in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001.								
	Ford Motor Company (Ford) is conducting a safety recall in accordance with the May 3, 2016 Amendment to the Consent Order for vehicle models listed and originally delivered or ever-registered in the Zones A, B, and C. The vehicles and model years affected for each zone are provided in a separate attachment.								

These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.

Production Dates: FEB 19, 2008 - JUL 25, 2010

VIN Range 1 : Begin : NR End: NR Not sequential

Description of Defect:

Description of the Defect: Updated December 7, 2018: This submission is to inform the Agency of Ford's

intent to implement the "Other" report category for removed vehicles in Quarterly Reporting as permitted in the Third Amendment to the Coordinated Remedy Order (ACRO3), paragraphs 45 through 49. As a condition of ACRO3, all affected vehicles will remain active, or "live," across Ford's data systems such that any search of "Other" removed VINs will return an open recall status. For this reason, the number of potential involved vehicles in this report will remain the same. However, for reference, initial counts of vehicles in the "Other" reporting category are indicated in the attached supplement. Note that these counts are current as of fourth calendar quarter of 2018. Future changes to overall Total Removed counts, including "Other" will be reflected in

quarterly reporting.

The passenger frontal airbag inflator could rupture if the vehicle is involved in a crash where the supplemental frontal airbags are designed to deploy. This defect report is in response to Takata defect information reports 18E-001, 18E-002, and 18E-003. Ford is not aware of any reports of accident or injury related to this condition associated with the inflators included in this recall.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The passenger frontal airbag inflator could rupture if the vehicle is involved

in a crash where the supplemental frontal airbags are designed to deploy. If an inflator ruptures, metal fragments could enter the passenger compartment

increasing the risk of injury or death to occupants.

Description of the Cause: NR Identification of Any Warning NR

that can Occur:

Supplier Identification:

Component Manufacturer

Name: TK Holdings

Address: 888 16th Street NW

Washington DISTRICT OF COLUMBIA 20006

Country: United States

Chronology:

On May 3, 2016, the Agency issued an Amendment to the November 3, 2015 Consent Order in EA15-001. The Agency has concluded that the rate at which propellant degradation may occur in non-desiccated frontal airbag inflators varies based upon geographic factors of environmental heat and humidity. In light of the Agency's findings, NHTSA has concluded that at some point in the future all non-desiccated frontal Takata PSAN inflators will reach a threshold level of degradation that could result in the inflator becoming unreasonably dangerous.

As directed in the May 3, 2016 amendment, on January 3, 2017, Takata issued three Defect Information Reports (18E-001-Zone A), (18E-002-Zone B), and (18E-003-Zone C) in accordance with the terms specified in the May 3, 2016 Amendment to the November 3, 2015 Consent Order in EA15-001. Takata is not aware of any test ruptures in ballistic testing or confirmed field incidents of the subject non-desiccated ammonium nitrate inflators other than those already under recall. Out of an abundance of caution, Takata filed the DIRs in cooperation with NHTSA to promote public Safety.

January 8, 2018, Ford's Field Review Committee reviewed the concern and approved a field action.

Description of Remedy:

Description of Remedy Program: Owners will be notified by mail and instructed to take their vehicle to a

Ford or Lincoln dealer to have their passenger frontal airbag inflator

replaced. There will be no charge for this service.

Ford will forward a copy of the notification letters to dealers to the agency

when available.

How Remedy Component Differs Remedy parts are currently under development.

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notification to dealers is expected to occur on January 17, 2018. Mailing

Part 573 Safety Recall Report

18V-046

Page 7

of owner notification letters is expected to begin on February 19, 2018,

and be completed on February 23, 2018.

Planned Dealer Notification Date : JAN 17, 2018 - JAN 17, 2018 Planned Owner Notification Date : FEB 19, 2018 - FEB 23, 2018

* NR - Not Reported