# Part 573 Safety Recall Report

Manufacturer Name :Mitsubishi Fuso Truck of America, Inc.Submission Date :JAN 11, 2018NHTSA Recall No. :18V-047Manufacturer Recall No. :MFV00001



18V-047

# Manufacturer Information :Population :Manufacturer Name :Mitsubishi Fuso Truck of America, Inc.Number of potentially involved :1,153Address :2015 Center Square RoadEstimated percentage with defect :100 %Logan Township NJ 08085999-99999100 %100 %

# Vehicle Information :

	2004-2017 MITSUBISHI FUSO FE84D, FE85D, FEC52, FEC72, FEC92, FGB72, FK61F, FM657 and
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES
Body Style :	ALL
Power Train :	DIESEL
Descriptive Information :	ALL TRUCKS THAT HAD THE FIRE EXTINGUISHER OPTION INSTALLED IN THE CAB ARE INCLUDED THE RECALL POPULATION. ALL TRUCKS THAT DID NOT HAVE A FIRE EXTINGUISHER OPTION INSTALLED ARE EXCLUDED.
Production Dates :	APR 03, 2003 - MAR 03, 2017
VIN Range 1:	Begin : JL6FFJ1E14K000521 End : JL6BNH1A7HK004957 📝 Not sequential

## **Description of Defect :**

Description of the Defect :	The fire extinguishers can become clogged or require excessive force to discharge and can fail to activate during a fire emergency. In addition, the nozzle can detach with enough force to pose an impact hazard.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	The extinguisher can fail to activate during a fire emergency. In addition, the nozzle can detach with enough force to pose an impact hazard.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR

### **Supplier Identification :**

#### **Component Manufacturer**

Name :Walter Kidde Portable Equipment CompanyAddress :1016 Corporate Park DrMebane NORTH CAROLINA 27302

Country: United States

#### **Chronology**:

Kidde is aware of a 2014 death involving a car fire following a crash. Emergency responders could not get the recalled Kidde fire extinguishers to work. There have been approximately 391 reports of failed or limited activation or nozzle detachment, including the fatality, approximately 16 injuries, including smoke inhalation and minor burns, and approximately 91 reports of property damage.

#### **Description of Remedy :**

How Remedy Component Differs from Recalled Component :Plastic handle fire extinguishers: The recall involves 134 models of Kidde fire extinguishers manufactured between January 1, 1973 and August 15, 2017, including models that were previously recalled in March 2009 and February 2015. The extinguishers were sold in red, white and silver, and are either ABC- or BC-rated. The model number is printed on the fire extinguisher label. For units produced in 2007 and beyond, the date of manufacture is a 10-digit date code printed on the side of the cylinder, near the bottom. Digits five through nine represent the day and year of manufacture in DDDYY format. Date codes for recalled models manufacture in DDDYY format. Date codes for recalled models manufacture in DDDYY format. Date codes for recalled models manufacture from January 2, 2012 through August 15, 2017 are 00212 through 22717. For units produced before 2007, a date code is not printed on the fire extinguisher. Push-button Pindicator fire extinguishers: The recall involves eight models of Kidde Pindicator fire extinguishers manufactured between August 11, 1995 and September 22, 2017. The no-gauge push-button extinguishers were sold in red and white, and with a red or black nozzle. These models were sold primarily for kitchen and personal watercraft applications.Identify How/When Recall Condition was Corrected in Production :NR	Description of Remedy Program :	Kidde will replace defective fire extinguishers by contacting Kidde toll-free at 855-271-0773 from 8:30 a.m. to 5 p.m. ET Monday through Friday, 9 a.m. to 3 p.m. ET Saturday and Sunday, or online at www.kidde.com and click on "Product Safety Recall" for more information.
		fire extinguishers manufactured between January 1, 1973 and August 15, 2017, including models that were previously recalled in March 2009 and February 2015. The extinguishers were sold in red, white and silver, and are either ABC- or BC-rated. The model number is printed on the fire extinguisher label. For units produced in 2007 and beyond, the date of manufacture is a 10-digit date code printed on the side of the cylinder, near the bottom. Digits five through nine represent the day and year of manufacture in DDDYY format. Date codes for recalled models manufactured from January 2, 2012 through August 15, 2017 are 00212 through 22717. For units produced before 2007, a date code is not printed on the fire extinguisher. Push-button Pindicator fire extinguishers: The recall involves eight models of Kidde Pindicator fire extinguishers manufactured between August 11, 1995 and September 22, 2017. The no-gauge push-button extinguishers were sold in red and white, and with a red or black nozzle. These models
	Identify How/When Recall Condition was Corrected in Production :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

#### **Recall Schedule :**

Description of Recall Schedule :	MFTA will notify dealers of the recall and customer notification on
	1/15/18, and release a notification to customers the same day.
Planned Dealer Notification Date :	JAN 15, 2018 - JAN 15, 2018
Planned Owner Notification Date :	JAN 15, 2018 - JAN 15, 2018

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573