

Part 573 Safety Recall Report

18V-073

Manufacturer Name : Jayco, Inc.**Submission Date :** JAN 29, 2018**NHTSA Recall No. :** 18V-073**Manufacturer Recall No. :** 9901373**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.

Address : 903 South Main Street

PO Box 460 Middlebury IN 46540

Company phone : 800-283-8267

Population :

Number of potentially involved : 461

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Jayco TT Eagle

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 320RLTS (EB) J1EB0051-0066
 338RETS (ED) J1ED0051-0194
 330RSTS (EA) JEA0051-0375

GVWR is noted on affected units as 11,750 while correct is noted on all future builds as 11,700

Production Dates : MAY 04, 2017 - DEC 20, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Correct GVWR of affected units is 11,700lb - but error made during data entry noted GVWR as 11,750lb.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Incorrect data on Labels pertaining GVWR

Description of the Cause : Data entry error - correct GVWR is on record as 11,700 lbs during data entry into program noted GVWR as 11,700lbs. Incorrect GVWR is noted on Federal labels and CCC lables

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

12-27-2017 was reported that GVWR information was incorrect on printed Federal Label and CCC Label was incorrect. During investigation Engineering found all information used to calculate the GVWR was correct but a data entry error had been made when printing Federal and CCC labels for the units. All units still on site were inspected and corrected labels placed on units prior to shipping. 1-25-18 Incident was reported to Corp. Safety Team for review - decided that RECALL was required.

Description of Remedy :

Description of Remedy Program : Corrected labels will be provided with recall notification letter for affected product. Jayco Dealer will replace at No Change or Current Retail owner can replace following provided instructions.

How Remedy Component Differs from Recalled Component : GVWR noted incorrect is 11,750 when correct is 11,700

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : We are prepared to release corrected labels to current owner on record upon receipt of recall number from NHTSA

Planned Dealer Notification Date : FEB 28, 2018 - FEB 28, 2018

Planned Owner Notification Date : FEB 28, 2018 - FEB 28, 2018

* NR - Not Reported