

Part 573 Safety Recall Report

18V-074

Manufacturer Name : Highland Ridge RV**Submission Date :** JAN 29, 2018**NHTSA Recall No. :** 18V-074**Manufacturer Recall No. :** 9904374**Manufacturer Information :**

Manufacturer Name : Highland Ridge RV

Address : 955 Tuscany Drive

Shipshewana IN 46565

Company phone : 260-768-7771

Population :

Number of potentially involved : 84

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2018-2018 Highland TT Open Range Light

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : 2018 Open Range Light 312BHS (TN)
J3TN3051-3142

Population was determined from production records of the 312BHS model when data error was found.

Information confirmed as correct for next run of production for the TN models affected.

Production Dates : SEP 11, 2017 - NOV 28, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Noncompliance :**

Description of the Noncompliance : Incorrect GAWR - printed on Federal Label - is noted as 5100# when the specified and correct axle installed is 4400# axle

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Incorrect aftermarket part could be installed on unit.

Description of the Cause : Data entry error when entering into the Master Records for this specific model.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

12-14-2017 During migration of data into new system - Engineer discovered axle information to print 2018 MY labels noted incorrect axle specified and installed on the TN model. None of the affected model was still on site to install corrected label. 1-25-18 Issue presented to Jayco Corp. Safety Steering Committee for review - decided a Recall was required

Description of Remedy :

Description of Remedy Program : Highland Dealers will install correct Federal Label at no charge to current owner on Record.
Current Owner on record can chose to apply corrected label, following Highland Instructions provided with Recall notification letter or contact Dealer to perform remedy at No charge .

How Remedy Component Differs from Recalled Component : GAWR noted as 5100# is incorrect - specified and correct axle installed is 4400lb axles.

Identify How/When Recall Condition was Corrected in Production : Immediate change in procedure for Engineering to confirm all label info is correct during prototype production before any labels are printed.

Recall Schedule :

Description of Recall Schedule : Highland will notify current owner on record to install new Federal label
-

Planned Dealer Notification Date : FEB 28, 2018 - FEB 28, 2018
Planned Owner Notification Date : FEB 28, 2018 - FEB 28, 2018

* NR - Not Reported