

PARTS DERESTRICTION NOTICE - SAFETY
RECALLS H081 AND N138 FUEL RAIL PARTS



NAS18.09.006 | PARTS

| CAN/USA

AFTERSALES BULLETIN

SEPTEMBER 13, 2018

To: Jaguar Land Rover Authorized Retailer Parts, Service, and General Managers

RE: Parts Derestriction Notice - Safety Recalls H081 and N138 Fuel Rail Parts

Please be advised that the part restrictions for the fuel rail parts supporting Safety Recalls H081 and N138, *Underhood Petrol Fuel Leak*, are being removed effective today. All open parts orders for these parts have been cancelled to help support this action and these parts can now be ordered normally.

Please order these parts carefully – do not over order these parts beyond your actual requirements to help maintain their availability. These parts will not be eligible for return via the Parts Buyback program.

Part Information:

- JDE40127..... Jaguar Fuel Rail
- T2H33724 Jaguar Injector Kits
- LR114169 Land Rover Fuel Rail
- LR105428 Land Rover Injector Kits

For questions regarding the content of this publication, please contact:

Campbell Mac Arthur Parts Operations Manager
(201) 818-8004 cmacarth@jaguarlandrover.com

Jaguar Land Rover North America, LLC
100 Jaguar Land Rover Way
Mahwah, NJ 07495