

Date: March 13, 2018

To: All Jaguar Land Rover USA Retailer Parts and Service Managers

Cc: Internal Distribution

Re: H081 and N138 AJ200P Fuel leaks - Safety Recall Parts Deployment Notification

Please be advised that Jaguar Land Rover USA is currently shipping initial parts allocations today to all Retailers with sold vehicles for the Jaguar H081 and Land Rover N138 Safety Recalls. Initial parts order allocations for fuel rails and injector kits are 30% based on sold Retailer vehicles. Priority for these parts should be given to customer sold units.

Due to supply constraints Jaguar Land Rover will be temporarily managing restricted parts orders until more supply is available to help maintain parts availability for all retailers and customers.

Retailers are requested to place future orders following the restricted parts order guidelines for each brand. Use the vehicle's VIN and quantity '1' fuel rail and quantity '4' injector kits per vehicle / per order. The VIN should be included on the 'Customer Material' line of the order. As with all restricted parts the orders will be reviewed and released multiple times each day. If the VIN is not included on the 'Customer material' line or a retailer orders more than 1' fuel rail and '4' injector kits per vehicle / per order the order will be cancelled with no notification.

Jaguar Land Rover thanks you for your cooperation to help us all manage through these important campaigns.