

## H081 and N138 Fuel Rail Recall N227 AEB Recall



### AJ20P Gasoline Engine - Fuel Rail Recalls

- Parts restrictions were removed September 13<sup>th</sup>
- N138 Land Rover completion rate c. 75% with 2,044 open USA VINs and 336 in Canada
- H081 Jaguar completion rate c 76 2,394 open USA VINs and 234 Canada
- About 250 units for each brand in retailer stock need repair
- Reminder: Not Eligible for Parts return (order only what you need)

### N227 - AUTONOMOUS EMERGENCY BRAKING (AEB) NOT AVAILABLE

Affects 86 USA and 3 Canadian vehicles. (One US unsold)

Recall was launched with the repair procedure October 1st . (Bulletin NAS18.10.001)

Affected Vehicles require a software update to the Image Processing Control Module (IPMA).  
(No Parts Required).

Customer notification will be on or before November 9th 2018.