

# Part 573 Safety Recall Report

# 18V-099

**Manufacturer Name :** Halcore Group, Inc.

**Submission Date :** FEB 08, 2018

**NHTSA Recall No. :** 18V-099

**Manufacturer Recall No. :** NR



## Manufacturer Information :

**Manufacturer Name :** Halcore Group, Inc.

**Address :** 3800 McDowell Road  
Grove City OH 43123

**Company phone :** 999

## Population :

**Number of potentially involved :** 640

**Estimated percentage with defect :** 70 %

## Vehicle Information :

**Vehicle 1 :** 2017-2017 American Emergency Vehicl Traumahawk Ambulance

**Vehicle Type :** BUSES, MEDIUM & HEAVY VEHICLES

**Body Style :** ALL

**Power Train :** NR

**Descriptive Information :** Customer reports of the Vanner Inc battery isolator module overheating in six vehicles that were produced May 5, 2017 through August 28, 2017.

**Production Dates :** APR 03, 2017 - SEP 28, 2017

**VIN Range 1 : Begin :**

NR

**End :** NR

☐ Not sequential

## Description of Defect :

**Description of the Defect :** Vanner Inc battery isolator module overheating.

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** Vanner Inc battery isolator module overheating can cause equipment circuitry failure & possibly fire.

**Description of the Cause :** Per Vanner Inc the root cause evaluation is in process.

**Identification of Any Warning that can Occur :** Inoperable on-board equipment, automotive relay clicking.

## Supplier Identification :

### Component Manufacturer

**Name :** Vanner Inc

**Address :** 4282 Reynolds Dr.

Hilliard OHIO 43026  
Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : NR

How Remedy Component Differs  
from Recalled Component : NR

Identify How/When Recall Condition  
was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported