

U.S. Department of Transportation

National Highway Traffic Safety Administration

March 5, 2018

Ms. Jennifer Shute Sr Mgr Safety Recall Execution Chrysler (FCA US LLC) 800 Chrysler Drive CIMS 482-00-91 Auburn Hills, MI 48326

Subject: Oil Pump Housing Crack may Cause Engine Stall

Dear Ms. Shute:

This letter serves to acknowledge Chrysler (FCA US LLC)'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NEF-150SM

18V-131

#### Makes/Models/Model Years:

JEEP/RENEGADE/2017

Mfr's Report Date: February 22, 2018

NHTSA Campaign Number: 18V-131

**Components:** 

ENGINE AND ENGINE COOLING: ENGINE

**Potential Number of Units Affected:** 9

# **Problem Description:**

Chrysler (FCA US LLC) is recalling certain 2017 Jeep Renegade vehicles equipped with a 2.4L engine. These vehicles may be equipped with a cracked oil pump housing/balance shaft module (BSM), which can cause the oil pump to fail and the engine to stall.

# **Consequence:**

An engine stall can increase the risk of a crash.

### Remedy:

Chrysler will notify owners, and dealers will inspect the oil pump for its production information, and replace the BSM as necessary, free of charge. The recall is expected to begin April 13, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U18.

#### Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



We have received Chrysler's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at (202) 366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

