



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

March 23, 2018

Mr. Hannes Zanon
Pagani Automobili SpA
Via dell'Artigianato, 5
San Cesario sul Panaro 41018

NEF-150JK
18V-175

Subject: Battery May Fail Causing Engine Stall or No Start

Dear Mr. Zanon:

This letter serves to acknowledge Pagani Automobili SpA's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

PAGANI/HUAYRA/2017

Mfr's Report Date: March 15, 2018

NHTSA Campaign Number: 18V-175

Components:

ELECTRICAL SYSTEM: SOFTWARE

ELECTRICAL SYSTEM: BATTERY

Potential Number of Units Affected: 16

Problem Description:

Pagani Automobili SpA (Pagani) is recalling all 2017 Huayra Coupe BC and Huayra Roadster vehicles. The battery management software may prevent the battery from providing enough power to start the car or keep the car running at idle.

Consequence:

An engine stall can increase the risk of a crash.

Remedy:

The remedy for this recall is still under development. The manufacturer has not yet provided a notification schedule. Owners may contact Pagani customer service at 1-415-350-7220.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please amend your Defect Information report to include Pagani's remedy plan once it has been determined.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

You are required to provide an estimated date including month, day, and year, when you will send notifications to owners, dealers, and distributors as soon as it becomes available. Please be reminded that it is required that owners be notified of a safety defect in their vehicles within 60 days of a manufacturer's notification to NHTSA of a safety defect in those vehicles.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement