



Re: RECALL- STOP-SALE Notice

March 2018

Dear Pagani Dealer,

Pagani Automobili has decided that on certain 2017 model year Pagani Huayra vehicles there is a possibility that, due to a problem in the battery management software, the 12Vcc battery may fail to provide enough power to the car. This could affect the car by the engine not starting, or by the car stalling when at idle, potentially increasing the risk of a crash.

The affected vehicles consist of Model Year 2017 Pagani Huayra Coupè BC and Huayra Roadster with the following VINs:

VIN	Model
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 1 U A	Coupe BC
Z A 9 H 1 2 U A	Roadster
Z A 9 H 1 2 U A	Roadster

Any Pagani Huayra not listed is not included in the recall and not affected by the STOP-SALE, therefore it will be possible to deliver under a sale or lease any Pagani Huayra not listed without any further action under this recall.

Pagani Automobili will repair the affected vehicles free of charge. The repair involves changing the battery, replacing it with a new one that has a new battery management software. The complete repair will take approximately 30 minutes.

Owners are being sent letters instructing them to contact their dealer for the repair. The earliest date on which Pagani reasonably expects that dealers will receive necessary parts and instructions is April 25th 2018.

New Vehicles In Dealer Inventory: It is a violation of Federal law for a dealer to deliver a new motor vehicles covered by this notification under a sale or lease until the defect is remedied.

Pre-Owned Vehicles in Dealer Inventory: Dealers are instructed not to delivery any pre-owned vehicles in their inventory which are involved in this recall until the defect has been remedied.

All replacement parts are available, and you will start receiving them starting from April 18th 2018.

All VINs included in the recall must be repaired per service bulletin no° 2 – 2018, prior to sale. Recall notice will be sent to the owners of the affected vehicles in the coming days.

Aftersales Department,
Pagani Automobili SpA