## **Recall Quarterly Report**

18V-177

Manufacturer Name: Mercedes-Benz USA, LLC.

NHTSA Recall No. / MFR Recall No.: 18V-177 /2018030012 Recall Subject: Rear Seat Belt May be Unable to be Latched

**Owner Notification Beginning Date:** APR 25, 2018

Owner Notification End Date: MAY 14, 2018



| Report # | Submission Date | Report<br>Quarter | Recall<br>Population | Total<br>Remedied | Total<br>Unreachable | Total<br>Removed |
|----------|-----------------|-------------------|----------------------|-------------------|----------------------|------------------|
| 4        | APR 27, 2019    | 2019-1            | 121,858              | 99,566            | 0                    | 0                |
| 3        | FEB 01, 2019    | 2018-4            | 121,858              | 89,476            | 0                    | 0                |
| 2        | OCT 17, 2018    | 2018-3            | 121,858              | 70,922            | 0                    | 0                |
| 1        | JUL 25, 2018    | 2018-2            | 121,858              | 46,009            | 0                    | 0                |

This Document Last Updated: MAY 01, 2019

## **Definitions:**

Report Quarter: The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the  $3^{rd}$  quarter of 2012). Recall Population: The total number of products recalled by the manufacturer.

Total Remedied: The total number of products either remedied, inspected without needing remedy, or returned to inventory.

Total Unreachable: Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed: Products that have been scrapped, stolen, or exported.