OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 18V-181

Manufacturer Name: Entegra Coach
Submission Date: MAR 19, 2018
NHTSA Recall No.: 18V-181

Manufacturer Recall No.: na



#### **Manufacturer Information:**

Manufacturer Name: Entegra Coach

Address: 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone: 1-800-945-4787

## **Population:**

Number of potentially involved: 130 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2011-2016 Class A motorhome Aspire Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : Power Train : NR

Descriptive Information: Per Daimler Trucks North America Recall notice FL727 18V163 affected chassis vin

listing - matched to Entegra unit serial numbers - created affected list of Aspire

motorhomes built on recalled chassis

Affects 2011 - 2012 Aspire Motorhomes AND

2015-2016 Aspire motor homes

Production Dates: MAR 08, 2010 - JAN 15, 2016

VIN Range 1 : Begin : NR End : NR Not sequential

#### **Description of Defect:**

Description of the Defect: Per Daimler - power steering hose may be routed with inadequate clearance

between the hose and a power stud on the starter motor. may cause the hose to rub against the power stud on the starter - leading to arcing and in addition

may cause a power steering fluid leak

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Per Daimler - Arcing in the presence of power steering fluid lead under high

pressure could increase the risk of a fire.

Description of the Cause: NR Identification of Any Warning NR

that can Occur:

## **Supplier Identification:**

## **Component Manufacturer**

Name: Damiler Trucks NOrth America

Address: PO Box 4090

Portland OREGON 97208

Country: United States

## **Chronology:**

Received Notification from Daimler pertaining to their recall Fl727 - matched vin listing to Entegra products built on the recalled chassis -

### **Description of Remedy:**

Description of Remedy Program: Per Daimler - Power steering hose will be rerouted for proper clearance to

starter stud by Daimler Trucks North American Authorized service

facilities.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: Daimler will release notification's to current owners, and Entegra will

provide current owner information to Daimler - Daimler will submit the 6

grtly reports to NHTSA - per Daimler release is scheduled May 2018

Planned Dealer Notification Date : MAY 07, 2018 - MAY 07, 2018

Planned Owner Notification Date: MAY 07, 2018 - MAY 07, 2018

<sup>\*</sup> NR - Not Reported