



REV Recreation Group  
P.O. Box 1007  
Decatur, IN 46733  
(800) 509-3417

**IMPORTANT RECALL INFORMATION #180322REV**

May 2018

**TO: ALL REV RECREATION GROUP DEALER PRINCIPALS,  
SERVICE MANAGERS AND PARTS MANAGERS**

**SUBJECT: RECALL CAMPAIGN #180322REV  
Satellite Dish Mounting**

REV Recreation Group, Inc., on behalf of its manufacturing center located in Decatur, Indiana, is requesting your assistance in conducting a voluntary recall notification campaign in accordance with the United States National Traffic and Motor Vehicle Safety Act and the Canada Motor Vehicle Safety Act.

REV Recreation Group, Inc., has decided that a safety defect relating to motor vehicle safety exists in certain model year 2018 Class A motorhomes equipped with an optional King Tailgater brand satellite dome:

**Fleetwood brand:**

- |                         |                          |
|-------------------------|--------------------------|
| 2018 Axon               | 2017-2018 Pace Arrow     |
| 2017-2018 Bounder       | 2017-2018 Pace Arrow LXE |
| 2017-2018 Discovery     | 2018 Pulse               |
| 2017-2018 Discovery LXE | 2017-2018 Southwind      |
| 2017-2018 Flair         | 2017-2018 Storm          |
| 2017-2018 Jamboree      |                          |

**Holiday Rambler brand:**

- |                        |                         |
|------------------------|-------------------------|
| 2017-2018 Admiral XE   | 2018 Reno               |
| 2017-2018 Endeavor     | 2017 Scepter            |
| 2017-2018 Endeavor XE  | 2017-2018 Vacationer    |
| 2017-2018 Navigator    | 2017-2018 Vacationer XE |
| 2017-2018 Navigator XE | 2017-2018 Vesta         |
| 2018 Prodigy           |                         |

**Monaco brand:**

- 2017 Diplomat
- 2018 Marquis

We are notifying the owners of the affected units in order to correct the problem. Copies of the letters sent to owners of record are attached for your information.

***WHAT IS THE PROBLEM?***

On motorhomes affected by this recall, the satellite dish was not properly secured to the roof and may come loose or detach. If the satellite dish detaches from the roof, it could present a road hazard, which may result in personal injury and/or property damage.

## **WHAT SHOULD YOU DO?**

Owners of the above mentioned motor homes have been asked to contact a REV Recreation Group dealer to have the described defect remedied. In the event that you are contacted by a customer, please verify eligibility by referring to the serial number range listed in the attached **Recall Service Bulletin #180322REV** prior to beginning repairs.

Once repairs have been completed according to **Recall Service Bulletin #180322REV**, have the customer sign your dealership's **Internal Repair Order**. Warranty labor claims are to be submitted electronically to REV Recreation Group. Customers will not be charged for these repairs.

If you have one of these vehicles in your inventory, you will be mailed a Safety Recall Notice for that specific motor home. REV Recreation Group dealers are required to make repairs to stock units on dealer lots prior to sale or lease.



**Federal Law (Section 154 of the National Highway Traffic and Motor Vehicle Safety Act) of 1966 requires that: If you have received a notice of recall or failure to comply from REV Recreation Group, Inc., or any component manufacturer, you must repair or otherwise correct the defect on vehicles remaining in your inventory according to the notification before selling or leasing the vehicles. Any vehicle lessor receiving this recall notice must forward a copy of the notice to the lessee within ten days.**

Please carefully review this entire package with your parts and service staff to familiarize them with the step-by-step procedure and implement the Voluntary Recall Campaign.

Thank you for helping REV Recreation Group with its continuing efforts to maintain customer satisfaction. If you have any questions, please contact your REV Recreation Group Service Center.

Sincerely,

**REV RECREATION GROUP, INC.**

Attachments: Recall #180322REV US Customer Letters  
Recall #180322REV Canadian Customer Letters  
Recall #180322REV Service Bulletin