



## IMPORTANT SAFETY RECALL

### AUTOCAR, LLC SAFETY RECALL ACX-1802

NHTSA RECALL NO. 18V-224

TC RECALL NO. 2018-175

May, 2018

**TO:** U.S. and Canadian Distributors

Dealer Principals, Service Managers, Warranty Managers, Parts Managers

This notice is being sent to you in accordance with the National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act.

Autocar, LLC, has decided that a defect which relates to motor vehicle safety exists in 2018-2019 model year Xpeditor chassis. These chassis were manufactured between 17 August 2017 and 8 March 2018, with non-sequential serial numbers in the range 224250 through 227368. Accordingly, a recall to address this issue is being initiated effective 25 May 2018.

**MODELS**

Autocar Xpeditor MY 2018-2019

**AFFECTED:**

**COMPONENTS**

Drag Link Clamp Pinch Bolt

**AFFECTED:**

**SAFETY DEFECTS  
AND POTENTIAL  
RISKS:**

The pinch bolt on the clamp for the adjustable length drag link was not properly torqued. If the pinch bolt is not properly torqued, the joint may experience premature wear and fail. Failure of the joint could cause a loss of steering control, increasing the risk of personal injury or property damage.

**REPAIR  
REQUIRED:**

The pinch bolt torque will be inspected and adjusted as needed.

**REPAIR  
AVAILABLE:**

VIN profiles in the Autocar Warranty System will be updated to show the open recall on 25 May 2018 and a spreadsheet of the affected VINs will be available in the Warranty system.

**REMINDER:**

It is a violation of Federal law to sell or lease a vehicle covered by this recall notice unless the recall remedy has been completed. Substantial civil penalties apply to violations of this law.

If you have any questions or concerns, please contact the Autocar Warranty Department at [warranty@autocartruck.com](mailto:warranty@autocartruck.com).

Sincerely,

**AUTOCAR, LLC**

ACF 00002 Rev. 000