This notice applies to your vehicle,

## U27/NHTSA 18V-231

### **LOGO**

## **VEHICLE PICTURE**

### YOUR SCHEDULING OPTIONS

- 1. Visit recalls.mopar.com to sign up for email or SMS notifications for when remedy parts become available. You will be asked to provide your Vehicle Identification Number (VIN), provided above
- **2.** Scan below using your smartphone or tablet to sign up to be notified when remedy parts become available

## **QR Code**

- **3.** Wait for FCA US to contact you again, by mail, with a follow-up recall notice when remedy parts are available
- 4. Call the FCA Recall Assistance
  Center at 1-800-853-1403. An
  agent can sign you up to be notified
  when remedy parts become
  available, or answer any other
  questions you may have

### DEALERSHIP INSTRUCTIONS

Please reference Safety Recall U27.

## IMPORTANT SAFETY RECALL

## **Under Body Ladder Rail**

Dear [Name],

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

FCA has decided that a defect, which relates to motor vehicle safety, exists in certain [2018 Model Year Jeep® Wrangler Unlimited] vehicles equipped with four doors.

#### WHY DOES MY VEHICLE NEED REPAIRS?

The driver's side rear under body ladder rail on your vehicle [1] may have been built with reduced corrosion protection which may, in certain circumstances, eventually result in a loose left rear seat mount or reduced strength of the rear floor pan due to premature corrosion. A loose left rear seat mount or reduced strength of the rear floor pan due to corrosion could, during a vehicle crash, allow two of the six attachment fasteners for the left rear seat to not be retained to the floor pan and/or the left rear floor pan structural frame member to buckle, which may increase the risk of injury.

#### HOW DO I RESOLVE THIS IMPORTANT SAFETY ISSUE?

The remedy for this condition is not currently available. We are making every effort to finalize the remedy and obtain parts as quickly as possible, and will service your vehicle free of charge (parts and labor).

FCA US will contact you again, by mail, with a follow-up recall notice when the remedy and/or parts are available. Once you receive your follow-up notice, simply contact your Chrysler, Jeep<sub>®</sub>, Dodge or RAM dealer right away to schedule a service appointment <sup>[2]</sup>. Additional options for your next steps are included on the left side of this notification. We appreciate your patience.

### WHAT IF I ALREADY PAID TO HAVE THIS REPAIR COMPLETED?

If you have already experienced this specific condition and have paid to have it repaired, you may visit <a href="www.fcarecallreimbursement.com">www.fcarecallreimbursement.com</a> to submit your reimbursement request online [3]. Once we receive and verify the required documents, reimbursement will be sent to you within 60 days. If you have had previous repairs performed and/or already received reimbursement, you may still need to have the recall repair performed.

We apologize for any inconvenience, but are sincerely concerned about your safety. Thank you for your attention to this important matter.

Customer Assistance/Field Operations FCA US LLC



# Mr. Mrs. Customer 1234 Main Street Hometown, MI 48371

<sup>[1]</sup> If you no longer own this vehicle, please help us update our records. Call the FCA Recall Assistance Center at 1-800-853-1403 to update your information.

<sup>[2]</sup> If your dealer fails or is unable to remedy this defect without charge and within a reasonable time, you may submit a written complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590, or you can call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to safercar.gov.

<sup>[3]</sup> You can also mail in your original receipts and proof of payment to the following address for reimbursement consideration: FCA Customer Assistance, P.O. Box 21-8004, Auburn Hills, MI 48321-8007, Attention: Recall Reimbursement.