

U.S. Department of Transportation

# National Highway Traffic Safety Administration

May 3, 2018

Mr. Andy Jones Daimler Trucks North America LLC 4747 N. Channel Ave. Portland, OR 97217 1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150MR 18V-250

Subject: Battery Cable Short may cause Fire

Dear Mr. Jones:

This letter serves to acknowledge Daimler Trucks North America LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

### Makes/Models/Model Years:

THOMAS BUILT BUSES/SAF-T-LINER C2/2018-2019

Mfr's Report Date: April 19, 2018

NHTSA Campaign Number: 18V-250

### **Components:**

ELECTRICAL SYSTEM:BATTERY:CABLES

Potential Number of Units Affected: 98

## **Problem Description:**

Daimler Trucks North America LLC (DTNA) is recalling certain 2018-2019 Thomas Built Buses Saf-T-Liner C2 transit buses equipped with 2 8D batteries. The battery power cable may have inadequate clearance between the cable and the battery hold down bracket when the battery tray is pulled out for service, causing the cable to rub against the bracket.

### **Consequence:**

The battery cable rubbing may cause the cable to short circuit, increasing the risk of a fire.

### Remedy:

DTNA will notify owners, and dealers will be inspect the battery cables and reroute them for proper clearance, as required, free of charge. The recall is expected to begin June 15, 2018. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL768.

#### **Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at (202) 366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

