

July 20, 2018

Mr. Todd Fronckowiak Assistant Director, Global Automotive Safety Compliance Ford Motor Company Fairlane Plaza South, Suite #500 330 Town Center Drive Dearborn, MI 48126-2738

Subject: Unintentional Rollaway Due to Detached Shift Cable

Dear Mr. Fronckowiak:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: FORD/ESCAPE/2013-2014 FORD/FUSION/2013-2016

Mfr's Report Date: July 16, 2018

NHTSA Campaign Number: 18V-471

Components: POWER TRAIN:AUTOMATIC TRANSMISSION:LEVER AND LINKAGE:FLOOR SHIFT

Potential Number of Units Affected: 504,182

Problem Description:

Ford Motor Company (Ford) is recalling certain 2013-2014 Ford Escape, and 2013-2016 Ford Fusion vehicles, equipped with sixspeed automatic transmissions. The bushing that attaches the transmission shifter cable to the transmission may degrade over time and cause the bushing to detach from the transmission. The condition could allow the driver to move the shift lever to Park and remove the ignition key, while the transmission may not be in Park, with no warning message or audible chime.

Consequence:

If the vehicle is exited without the transmission being in Park and without the parking brake being applied, the vehicle may unexpectedly move, increasing the risk of a crash.

Remedy:

Ford will notify owners, and dealers will replace the shifter cable bushing, free of charge. The recall is expected to begin July 30, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S20. Note: Owners are directed to use the parking brake until the recall remedy repairs can be made.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



1200 New Jersey Avenue SE Washington, DC 20590

> NEF-150JK 18V-471

We have received Ford's proposed owner notification letter and it is currently under review. You will be notified of any changes or concerns once our review is complete.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Jennifer Kruger who may be reached by phone at (202) 366-2461, or by email at jennifer.kruger@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian Chief, Recall Management Division Office of Defects Investigations Enforcement

