Next Unread Message

View Message



DATE: September 12, 2018

TO: All Acura Parts & Service Managers, Advisors, and Personnel

FROM: Brad Ortloff, Manager of Auto Campaigns and Recalls

RE: 2017-18 NSX Stop Sale & Safety Recall Updates

On September 7, 2018, American Honda notified NHTSA of a safety recall and stop sale for all 2017 and a small number of 2018 NSX units due to fuel tanks that may leak at the crossover inlet pipe weld joint. Additionally, American Honda notified NHTSA of a safety recall and stop sale notification for some 2017 NSX units due to center high mount stop lights that may fail. Refer to your eResponsibility report or do an iN VIN inquiry status to determine which units in your inventory are affected.

Failure to repair a vehicle as necessary prior to sale may subject your dealership to claims or lawsuits.

As of today, September 12, 2018, the following service bulletins have been revised with repair procedure, parts, tools and warranty claim information and posted to the Service Information System:

- 18-050: Safety Recall: NSX Fuel Tank / Product Update: Thermostat
- 18-053: Safety Recall: NSX Fuel Tank
- 18-049: Safety Recall: High Mount Brake Light

Parts to support repairs covered by 18-050 and 18-053 are expected to be on hand and available for dealer ordering by September 14, 2018. Tools to support these repairs should be in dealer inventory, and are also available for ordering through the Special Tools program.

Parts to support repairs covered by 18-049 are available now for dealer ordering. Drill bits and bit stops have been distributed to all dealers, with most expected to have arrived on September 11, 2018.

As always, be sure to do an iN VIN status inquiry for all vehicles passing through your dealership to determine eligibility for any open campaigns.